

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/20/2024

Submitted Date:

05/23/2024

Document Number:

699700384

FIELD INSPECTION FORM

Loc ID 334971 Inspector Name: Heil, John On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257247	WELL	PR	05/15/2000	GW	045-07416	PA 14-32	EI
276430	WELL	PR	09/13/2011	OW	045-10458	PA 614-32	EI
447955	SPILL OR RELEASE	CL	05/02/2019		-	SPILL/RELEASE POINT	EI

General Comment:

[ECMC Environmental Inspection.](#)

Inspected Facilities

Facility ID: 257247 Type: WELL API Number: 045-07416 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 276430 Type: WELL API Number: 045-10458 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 447955 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Stormwater ponding on the northeast section of the location.](#)

Corrective Action: **Comply with Rule 1002.f.(2)- Install or repair required stormwater and erosion control BMPs to properly divert stormwater runoff, and well as to stabilize the working pad surface, and to minimize tracking and off-site sediment transport.**

Ensure BMPs are installed in accordance with good engineering practices and maintained in a proper functioning condition; ongoing stormwater management required until Location receives a passing final reclamation inspection.

Date: 05/30/2024

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700385	20240520 Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6559602