

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/15/2024

Submitted Date:

05/23/2024

Document Number:

710500280

FIELD INSPECTION FORM

Loc ID 307275 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Costa, Ryan		ryan.costa@state.co.us	
BACA, DAVE	719-859-4066	dbaca@ogrisop.com	All Inspections
Zeches, Giena	719-220-4041	gzeches@ogrisop.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
113669	PIT	AC			-	APACHE CANYON 3-15	EI
217349	WELL	TA	08/15/2013	CBM	071-06125	APACHE CANYON 3-15	EI
307275	LOCATION	AC			-	APACHE CANYON-634S68W 3SWSE	EI

General Comment:

This is an Environmental Inspection for the Apache Canyon 03-15, well location Located in Las Animas County CO. Remediation Project # 29778

Location

Lease Road:			
	Type	Access	
comment:	There is a sign at the start of the access road stating, "Reclamation Area do not disturb". Water bars were installed along access road.		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
	Type		
Comment:	Well Placard is on site.		
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type:	#		
Comment:	Surface Equipment was removed.		
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 113669 Type: PIT API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 217349 Type: WELL API Number: 071-06125 Status: TA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 307275 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: Surface Equipment was removed from the location. It appears the location and access road were reseeded. There is an ongoing Remediation, Project # 29778 for the location. Operator will continue quarterly reporting until the site investigation is complete and Full Table 915-1 standards are met within the remediation area

Corrective Action: _____

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
-------	--------	---------	------	-------

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: [There is an Active Pit Facility on the location, Pit Facility ID 113669. Operator shall provide a Form 27 Document or correspondence related to the closure of the pit in the next Form 27 Submittal](#)

Corrective Action:

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action:

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action:

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action:

Date: _____

ECMC Comments

Comment	User	Date
ECMC conducted an inspection for Remediation Project # 29778. Operator will continue quarterly reporting until the site investigation is complete and Full Table 915-1 standards are met within the remediation area	sanchezcc	05/23/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500281	Inspection 710500280 Location Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6559801