

Inspection Photos

May 21st 2024

Operator: Enduring Resources LLC - 10663

Location ID: 326325

Inspection Document #: 714000779

La Plata County, CO

Township: SWSE 8 34N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO


**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: W. Animas Wheeler 8-1
Location ID: 326325



Photo 1. View of the well pad taken from the access point facing center.



API #: 067-07841

Inspection Photos

Location Name: W. Animas Wheeler 8-1

Location ID: 326325



Photo 2. Storm water corrective action identified in the previous inspection doc #714000030 has been addressed/resolved.

Inspection Photos

Location Name: W. Animas Wheeler 8-1

Location ID: 326325



Photo 3. Storm water corrective action identified in the previous inspection doc #714000030 has been addressed/resolved.

Inspection Photos

Location Name: W. Animas Wheeler 8-1

Location ID: 326325



Photo 4. Weedy kochia debris corrective action identified in the previous inspection doc #714000030 has been addressed/resolved.

Inspection Photos

Location Name: W. Animas Wheeler 8-1

Location ID: 326325



Photo 5. Large patches of cheatgrass observed in the eastern portion of the disturbance along the fill slopes.

Inspection Photos

Location Name: W. Animas Wheeler 8-1

Location ID: 326325



Photo 6. View of the reference area comprised of rabbitbrush, indian rice grass, mountain mahogany and juniper.