

Inspection Photos

05/20/2024

Operator: GUNNISON ENERGY LLC - 10515

Location ID: 453805

Inspection Doc: 696205840

Gunnison County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 453805



Photo 1: Photos taken from the access road. Photo left shows Location signage has been removed. Photo right example showing noxious weeds observed establishing along the access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 453805



Photo 2: Photo taken from the north end of the Location, facing south. Photo shows stormwater and erosion controls remain missing or insufficient at the cut slopes; slope is bare, exposed and at risk to wind and water erosion. It is noted that there are areas where vegetation is establishing on the cut slopes, however this appears to be from seed within topsoil sediment that has been eroded/transported from the unstabilized stockpile, onto the cut slope during runoff events.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 453805



Photo 3: Continued from photo 2- There are areas where vegetation is establishing on the cut slopes, however this appears to be from seed within topsoil sediment that has been eroded/transported from the unstabilized stockpile, onto the cut slope during runoff events.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 453805



Photo 4: Photos examples showing BMPs to protect the topsoil stockpile have not been installed or maintained in proper functioning condition. Photo right also example showing noxious weed establishment at the topsoil stockpile (Musk thistle).



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 453805



Photo 5: Photo taken from the topsoil stockpile. Photo example showing noxious weed establishment at the topsoil stockpile (Musk thistle).

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 453805



Photo 6: Photo taken from the fill slopes. Photo shows vegetative establishment at the fill slopes appears uniform. Immediate stormwater and erosion issues not apparent at fill slopes.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources