

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/23/2024

Submitted Date:

05/23/2024

Document Number:

694500662

FIELD INSPECTION FORM

Loc ID 313331 Inspector Name: NEIDEL, KRIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10396
Name of Operator: SWN PRODUCTION COMPANY LLC
Address: P.O. BOX 12359
City: SPRING State: TX Zip: 77391-

Findings:

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Longworth, Mike		michael.longworth@state.co.us	
Snowden, Russ		Russ_Snowden@swn.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
483200	Flowline System	AC	11/08/2022		-	Lay creek	EI

General Comment:

On 5/23/2024, ECMC staff inspected the Encore Field (Sombrero Ranch) flowlines in preparation of abandonment. The flowline risers are observable penetrating the ground in the same state as when they were in use. Soil samples shall be collected at each riser or launcher/receiver for Table 915-1. See attached photos. NOTE: two inspections were entered for this facility id to document the two ends of the flowline.

Inspected Facilities

Facility ID: 483200 Type: Flowline API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500663	photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6560413