

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/15/2024

Submitted Date:

05/23/2024

Document Number:

710500282**FIELD INSPECTION FORM**Loc ID 307314 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10758Name of Operator: OGRIS OPERATING LLCAddress: PO BOX 53467City: MIDLAND State: TX Zip: 79710**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Zeches, Giena	719-220-4041	gzeches@ogrisop.com	
Costa, Ryan		ryan.costa@state.co.us	
Dave Baca		dbaca@ogrisop.com	Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217442	WELL	TA	08/15/2013	GW	071-06219	APACHE CANYON 10-2	EI
307314	LOCATION	AC			-	APACHE CANYON-634S67W 10NWNE	EI

General Comment:

This is an Environmental Inspection for the Apache Canyon 10-02, well location Located in Las Animas County CO. Remediation Project # 29780

Location				
Lease Road:				
Type				
comment:	Drive through location			
Corrective ActionL			Date:	
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:	Well Placard onsite			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				corrective date
Type:	#			
Comment:	Surface Equipment associated with the Apache Canyon 10-02 was removed. There is an active Drip on the location for the an Active flowline running through the location			
Corrective Action:				Date:
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	217442	Type:	WELL	API Number:	071-06219	Status:	TA	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	307314	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental

Spill/Remediation:

Comment:

Surface Equipment was removed from the location. There is an ongoing Remediation, Project # 29780 for the location. Operator will continue quarterly reporting until the site investigation is complete and Full Table 915-1 standards are met within the remediation area

Corrective Action:

Date:

Emission Control Burner (ECB):

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

ECMC Comments		
Comment	User	Date
There is an area located on the well pad with no vegetation growth. Operator shall comply with Rule 1004 for final reclamation.	sanchezcc	05/23/2024
ECMC conducted an inspection for Remediation Project # 29780. Operator will continue quarterly reporting until the site investigation is complete and Full Table 915-1 standards are met within the remediation area	sanchezcc	05/23/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500283	Inspection 710500282 Location Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6560417