

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/23/2024

Submitted Date:

05/24/2024

Document Number:

707602844**FIELD INSPECTION FORM**Loc ID 310057 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295832	WELL	SI	07/01/2022	GW	123-25817	PEPPLER 17-22	PA

**General Comment:**

This is a **PLUGGED & ABANDONED WELL / WORKOVER / CEMENTING** inspection.

Well(s): 1: Plugged & Abandoned | PA.

Plugging Operations: Cementing; Cement-surface.

Battery: Inactive. Shut-down.

Inactive Battery SE corner GPS coordinates: 40.489739 / -104.465512

Well GPS coordinates: 40.488670 / -104.462940

**Location****Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Jobsite entrance & safety signage posted.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 0		corrective date
Comment:	Plugged & Abandoned   PA. Equipment removed.		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	295832	Type:	WELL	API Number:	123-25817	Status:	SI	Insp. Status:	PA
Cement									
Cement Contractor									
Contractor Name: Duco Services					Contractor Phone:				
Surface Casing									
Cement Volume (sx):					Circulate to Surface:				
Cement Fall Back:					Top Job, 1" Volume:				
Intermediate Casing									
Cement Volume (sxs):					Good Return During Job:				
Production Casing									
Cement Volume (sx):					Good Return During Job:				
Plugging Operations									
Depth Plugs(feet range): 2564'-0'					Cement Volume (sx): 474 sxs				
Good Return During Job: YES					Cement Type: Class "G" Neat 15.8#				
Comment: 2024/05/23: Plugging Operations: Cementing; cement-surface. 2024/53/23: JSA attached as photo to this report.  Workover Contractor: Ensign Energy Services Rig #314. Cement Contractor: Duco Services.  PRE JOB SAFETY MEETING AND JSA. CHECK PRESSURES. SICP 0PSI. SIBHP 0PSI. FUNCTION TEST BOP. TEST GOOD. RD WORK FLOOR AND HANDLING EQUIPMENT. ND BOP AND WORK SPOOL. REMOVE 5K WELL HEAD AND SURFACE CAP. PU STS 4.5" SPEAR. UNLAND CASING. STRIP OVER LARKIN ADPATER FLANGE, WORK SPOOL AND BOP. RU WORK FLOOR AND HANDLING EQUIPMENT. LD 56 AND A PARTIAL OF 4.5" 11.6# CASING. MU/TH WITH MULE SHOE AND 80 JOINTS OF 2-3/8" FROM DERRICK. PU 3 JOINTS. TIE IN PUMP LINES. CIRCULATED WELL CLEAN OF ALL OIL, GAS AND HEAVY MUD. MIRU DUCO CEMENT. HELD SAFETY MEETING. PUMP 5BBLs FW AHEAD. PUMP/MIX 100SXS (20.4BBLs) G-NEAT 15.8# CEMENT FROM 2564'-2300'. MAINTAINED GOOD CIRCULATION THROUGHOUT JOB. LD 35 JOINTS OF 2-3/8". PUMP/MIX 100SXS (20.4BBLs) G-NEAT 15.8# CEMENT FROM 1483'-1280'. MAINTAINED GOOD CIRCULATION THROUGHOUT JOB. LD 25 JOINTS OF 2-3/8". PUMP/MIX 254SXS (52.1BBLs) G-NEAT 15.8# CEMENT FROM 710'-SURFACE. RETURNED BACK 1BBL CEMENT. RD CEMENTERS. LD 23 JOINTS OF 2-3/8". TIE CEMENTERS INTO CASING VALVE. TOP WELL OFF WITH 20SXS (4BBLs) G-NEAT 15.8# CEMENT. GOOD CEMENT. RD WASH UP CEMENTERS. RD WORK FLOOR AND HANDLING EQUIPMENT. ND BOP, WORK SPOOL AND LARKIN ADAPTER FLANGE. MU SURFACE CAP. SWI. CREW CLEANED LOCATION. CREW TRAVELED HOME. WELL IS P&AD.									
Corrective Action:					Date:				
Workover									
Comment:									

<p>2024/03/13: Plugging Operations: Cementing; cement-surface. 2024/05/23: JSA attached as photo to this report.</p> <p>Workover Contractor: Ensign Energy Services Rig #314. Cement Contractor: Duco Services.</p> <p>Reference: Form 6N on file. Notice of Intent to Abandon date: 10/23/2023. Approved. Form 42 on file. Notice of MIRU. Start Date: 05/21/2024. Approved. Form 42 on file. Notice of Plugging Operations. Start Date: 05/22/2024. Approved.</p>		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On THU 05/23/2024 at approximately 12:25 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: PDC ENERGY INC Location Name: PEPPLER-66N63W/17SEnw Location ID: 310057 Well Name(s): Peppler 17-22. API: 123-25817. Location County: Weld County, Colorado Weather: Mostly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged &amp; Abandoned   PA. Plugging Operations: Cementing; Cement-surface. Battery: Inactive. Shut-down. Inactive Battery SE corner GPS coordinates: 40.489739 / -104.465512 Well GPS coordinates: 40.488670 / -104.462940</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	05/24/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602845	Site photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6561194">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6561194</a>