

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/23/2024

Submitted Date:

05/24/2024

Document Number:

707602844

FIELD INSPECTION FORM

Loc ID 310057 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295832	WELL	SI	07/01/2022	GW	123-25817	PEPPLER 17-22	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL / WORKOVER / CEMENTING** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Plugging Operations: Cementing; Cement-surface.
Battery: Inactive. Shut-down.
Inactive Battery SE corner GPS coordinates: 40.489739 / -104.465512
Well GPS coordinates: 40.488670 / -104.462940

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Jobsite entrance & safety signage posted.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Plunger Lift	# 0		corrective date
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:		Date:	
Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 295832 Type: WELL API Number: 123-25817 Status: SI Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Duco Services Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 2564'-0' Cement Volume (sx): 474 sxs

Good Return During Job: YES Cement Type: Class "G" Neat 15.8#

Comment: 2024/05/23:
 Plugging Operations: Cementing; cement-surface.
 2024/53/23: JSA attached as photo to this report.

Workover Contractor: Ensign Energy Services Rig #314.
 Cement Contractor: Duco Services.

PRE JOB SAFETY MEETING AND JSA. CHECK PRESSURES. SICP 0PSI. SIBHP 0PSI. FUNCTION TEST BOP. TEST GOOD. RD WORK FLOOR AND HANDLING EQUIPMENT. ND BOP AND WORK SPOOL. REMOVE 5K WELL HEAD AND SURFACE CAP. PU STS 4.5" SPEAR. UNLAND CASING. STRIP OVER LARKIN ADPATER FLANGE, WORK SPOOL AND BOP. RU WORK FLOOR AND HANDLING EQUIPMENT. LD 56 AND A PARTIAL OF 4.5" 11.6# CASING. MU/TIH WITH MULE SHOE AND 80 JOINTS OF 2-3/8" FROM DERRICK. PU 3 JOINTS. TIE IN PUMP LINES. CIRCULATED WELL CLEAN OF ALL OIL, GAS AND HEAVY MUD. MIRU DUCO CEMENT. HELD SAFETY MEETING. PUMP 5BBLs FW AHEAD. PUMP/MIX 100SXS (20.4BBLs) G-NEAT 15.8# CEMENT FROM 2564'-2300'. MAINTAINED GOOD CIRCULATION THROUGHOUT JOB. LD 35 JOINTS OF 2-3/8". PUMP/MIX 100SXS (20.4BBLs) G-NEAT 15.8# CEMENT FROM 1483'-1280'. MAINTAINED GOOD CIRCULATION THROUGHOUT JOB. LD 25 JOINTS OF 2-3/8". PUMP/MIX 254SXS (52.1BBLs) G-NEAT 15.8# CEMENT FROM 710'-SURFACE. RETURNED BACK 1BBL CEMENT. RD CEMENTERS. LD 23 JOINTS OF 2-3/8". TIE CEMENTERS INTO CASING VALVE. TOP WELL OFF WITH 20SXS (4BBLs) G-NEAT 15.8# CEMENT. GOOD CEMENT. RD WASH UP CEMENTERS. RD WORK FLOOR AND HANDLING EQUIPMENT. ND BOP, WORK SPOOL AND LARKIN ADAPTER FLANGE. MU SURFACE CAP. SWI. CREW CLEANED LOCATION. CREW TRAVELED HOME. WELL IS P&A'D.

Corrective Action: _____ Date: _____

Workover

Comment:

2024/03/13:
Plugging Operations: Cementing; cement-surface.
2024/05/23: JSA attached as photo to this report.

Workover Contractor: Ensign Energy Services Rig #314.
Cement Contractor: Duco Services.

Reference:
Form 6N on file. Notice of Intent to Abandon date: 10/23/2023. Approved.
Form 42 on file. Notice of MIRU. Start Date: 05/21/2024. Approved.
Form 42 on file. Notice of Plugging Operations. Start Date: 05/22/2024. Approved.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On THU 05/23/2024 at approximately 12:25 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: PDC ENERGY INC Location Name: PEPPLER-66N63W/17SENW Location ID: 310057 Well Name(s): Peppler 17-22. API: 123-25817. Location County: Weld County, Colorado Weather: Mostly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Plugging Operations: Cementing; Cement-surface. Battery: Inactive. Shut-down. Inactive Battery SE corner GPS coordinates: 40.489739 / -104.465512 Well GPS coordinates: 40.488670 / -104.462940</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	05/24/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403803045	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6561200
707602845	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6561194