

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403766474

Date Received:

05/21/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 708301980

Inspection Date: 04/04/2024

FIR Submit Date: 04/06/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

### LOCATION - Location ID: 334816

Location Name: MV Number: 34-5 County: \_\_\_\_\_

Qtrqtr: LOT 7 Sec: 5 Twp: 7S Range: 96W Meridian: 6

Latitude: 39.460994 Longitude: -108.125589

### FACILITY - API Number: 05-045- -00 Facility ID: 334816

Facility Name: MV Number: 34-5

Qtrqtr: LOT 7 Sec: 5 Twp: 7S Range: 96W Meridian: 6

Latitude: 39.460994 Longitude: -108.125589

### CORRECTIVE ACTIONS:

1 ☒ CA# 194071

Corrective Action: Secure load line to comply with Rule 608.e.

Date: 04/11/2024

Response: CA COMPLETED

Date of Completion: 04/10/2024

Operator Comment: Load line is now plugged. Corrective Action complete.

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

2 ☒ CA# 194072

Corrective Action: Remove debris to comply with Rule 606.

Date: 11/09/2023

Response: CA COMPLETED

Date of Completion: 04/10/2024

Operator  
Comment: Debris has been removed from the location. Corrective Action complete.

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

3 ☒ CA# 194073

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 04/21/2024

Response: CA COMPLETED

Date of Completion: 05/20/2024

Operator  
Comment: Pad has been bladed/graded to remove rutting. Corrective action complete.

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA #194071: Load line is now plugged. Corrective Action complete.  
CA #194072: Debris has been removed from the location. Corrective Action complete.  
CA #194073: Pad has been bladed/graded to remove rutting. Corrective action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed:

Title: TEP Representative

Date: 5/21/2024 11:40:18 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403766474	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files