

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC MOBIL W-20-32 Pad

Location ID: 311555



May 23, 2024 at 8:55:37 AM
CO

Photo # 8091 From entrance to location



May 23, 2024 at 8:56:41 AM
CO

Photo # 8092 Location

Location Name: TEP ROCKY MOUNTAIN LLC MOBIL W-20-32 Pad
Location ID: 311555

Location Name: TEP ROCKY MOUNTAIN LLC MOBIL W-20-32 Pad
Location ID: 311555



Photo # 8093 Location



Photo # 8094 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBIL W-20-32 Pad

Location ID: 311555



Photo # 8095 Location



Photo # 8096 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBIL W-20-32 Pad

Location ID: 311555



Photo # 8097 Wellhead cellar lacks wildlife protection /wildlife hazard/available for entry by wildlife. Cellar also lacks wildlife egress.



Photo # 8098 Wellhead cellar lacks wildlife protection /wildlife hazard/available for entry by wildlife. Cellar also lacks wildlife egress.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBIL W-20-32 Pad

Location ID: 311555



Photo # 8099 Wellhead cellar lacks wildlife protection /wildlife hazard/available for entry by wildlife. Cellar also lacks wildlife egress.



Photo # 8100 Wellhead cellar lacks wildlife protection /wildlife hazard/available for entry by wildlife. Cellar also lacks wildlife egress.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBIL W-20-32 Pad

Location ID: 311555



Photo # 8101 Production tank damaged



Photo # 8102 Production tank damaged