


Storm Water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC WASATCH BENCH WATER MGMT FACILITY

Location ID: 414907



Location Overview: Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area. Location is within Rule 411a Surface Water Internal & Intermediate Buffers. Location is approximately 222 yards from Mamm Creek.

Section/Township/Range: 20 6S92W

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC WASATCH BENCH WATER MGMT FACILITY

Location ID: 414907



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC WASATCH BENCH WATER MGMT FACILITY

Location ID: 414907



Photo # 8202 Stockpiled soils with no BMP's



Photo # 8203 Stockpiled soils with no BMP's

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC WASATCH BENCH WATER MGMT FACILITY

Location ID: 414907



Photo # 8204 Stockpiled soils with no BMP's (S/SW corner)



Photo # 8205 Stockpiled soils with no BMP's (S/SW corner)

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC WASATCH BENCH WATER MGMT FACILITY

Location ID: 414907



Photo # 8206 Lack of stabilization/compaction



Photo # 8207 Lack of stabilization/compaction

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC WASATCH BENCH WATER MGMT FACILITY

Location ID: 414907



Photo # 8208 Lack of stabilization/compaction



Photo # 8209 Lack of stabilization/compaction

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC WASATCH BENCH WATER MGMT FACILITY

Location ID: 414907



Photo # 8210 Erosion & transport of sediment (East side of location)



Photo # 8211 Erosion & transport of sediment into a vegetated area (East side of location)

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC WASATCH BENCH WATER MGMT FACILITY

Location ID: 414907



Photo # 8212 Erosion & transport of sediment into a vegetated area (East side of location)



Photo # 8213 Erosion & transport of sediment into a vegetated area (E/SE area of location)

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC WASATCH BENCH WATER MGMT FACILITY

Location ID: 414907



Photo # 8214 Erosion & transport of sediment into a vegetated area (E/SE area of location)