

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403804361

Date Received:

05/28/2024

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

3 of 4 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10797

Name of Operator: DESERT EAGLE OPERATING LLC

Address: 17101 PRESTON RD SUITE 105

City: DALLAS State: TX Zip: 75248

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

Joe Nemecek

580-421-6921

jnemecek@jsxchange.com

Bulf. Cathy

719-440-9906

cathybulf@gmail.com

Butler. Brad

972-345-9195

butleroil@yahoo.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 713600975

Inspection Date: 04/22/2024

FIR Submit Date: 04/24/2024

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: DESERT EAGLE OPERATING LLC

Company Number: 10797

Address: 17101 PRESTON RD SUITE 105

City: DALLAS State: TX Zip: 75248

#### LOCATION - Location ID: 484358

Location Name: Red Rocks

Number: 1-16

County: LAS ANIMAS

Qtrqtr: NENE

Sec: 1

Twp: 30S

Range: 55W

Meridian: 6

Latitude: 37.464488

Longitude: -103.518825

#### FACILITY - API Number: 05-071-

-00

Facility ID: 484677

Facility Name: Red Rocks

Number: 1-16

Qtrqtr: NENE

Sec: 1

Twp: 30S

Range: 55W

Meridian: 6

Latitude: 37.464488

Longitude: -103.518825

### CORRECTIVE ACTIONS:

1 CA# 194648

Corrective Action: Comply with Rule 902.b. Install or repair wildlife protection equipment.

Date: 05/01/2024

Response: CA COMPLETED

Date of Completion: 04/29/2024

Operator  
Comment:

The chemical fuel containers and secondary containment units were no longer required and have been removed from the location. A game fence is installed around the compressor for wildlife protection. Rule 902.b. Photos attached.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative: \_\_\_\_\_

2 CA# 194649

Corrective Action: Comply with Rule 606.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 04/29/2024

Operator  
Comment: Tree debris along the flowline and at the location has been removed. Rule 606. Photos attached.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative: \_\_\_\_\_

4 CA# 194651

Corrective Action: Comply with 1002.f.(2).B.D Conduct maintenance on equipment, cleanup stained material, and review self inspection processes.

Date: 04/26/2024

Response: CA COMPLETED

Date of Completion: 04/29/2024

Operator  
Comment: Rule 1002.f.(2).B.D. Unnecessary equipment that originally had secondary containment has been removed from location. Stained soils and materials have been cleaned up. Third party vendors have been instructed on proper maintenance of the location. Desert Eagle personnel have reviewed the self inspection process. Rule 1002.f (2).B,D Phots attached.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Desert Eagle Operating (DEO) endeavors to operate in a manner that protects public health, safety, welfare, the environment and wildlife resources by complying with all the rules and regulations of the ECMC. In response to the this Field Inspection form, DEO provides the following: The chemical fuel containers and secondary containment units were no longer required and have been removed from the location. A game fence is installed around the compressor for wildlife protection. Rule 902.b. Photos attached. Tree debris has been removed and bermed areas along the road have been stabilized Rule 606. Photos attached. Stained soils around the compressor engine have been cleaned up. Oily fluids in the engine skid mount and inside secondary containment was removed. Third party personnel have been instructed on good housekeeping practices and Desert Eagle Operating (DEO) personnel have reviewed self-inspection processes. Rule 1002.f.(2) B.D. Photos attached. Areas of the location were prepared and seeded; however, sparse germination has been attributed to several factors: lack of rain, lack of topsoil/soil amendments, and remaining areas of heavily compacted soils. DEO is preparing to address these issues with additional soil ripping, applying additional topsoil, and reseeding. DEO continues to evaluate the identified drill cuttings waste and clean up at the north side of the location and is proceeding with drill cuttings clean up under Form 27. Updated FIRR's will be submitted upon completion.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cathy Bulf

Signed: \_\_\_\_\_

Title: Manager

Date: 5/28/2024 11:30:02 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403804631	Photo - R 1-16 Wildlife Protection
403804641	Photo - RR 1-16 Tree Debris Removed, Berms Stabilized

403804647	Photo - RR 1-16 Oily Fluids Removed in Engine Skid and Inside Secondary Containment
403804650	Photo - RR 1-16 Stained Soils Cleaned Up Around Engine Compressor
403804654	Photo - RR 1-16 Stained Soil Cleaned Up Near Compressor Engine

Total Attach: 5 Files