

Inspection Photos

May 24th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325351

Inspection Document #: 714000789

La Plata County, CO

Township: SENW 16 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Craig 1, 3
Location ID: 325351



Photo 1. View of the well disturbance taken from the southern edge facing center.

Inspection Photos
Location Name: Craig 1, 3
Location ID: 325351




Photo 2. Musk thistle observed on location.

Inspection Photos
Location Name: Craig 1, 3
Location ID: 325351



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Storm water corrective action identified in the previous inspection doc #714000033 has been addressed/resolved.

API #: 067-06223, 09732

Inspection Photos
Location Name: Craig 1, 3
Location ID: 325351



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Large patches of field bindweed were observed throughout the western interim reclamation area.

API #: 067-06223, 09732

Inspection Photos
Location Name: Craig 1, 3
Location ID: 325351

5/24/24
+37.194642,-107.834827
32° NE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Weedy vegetation observed at active equipment and berms on location.

API #: 067-06223, 09732

Inspection Photos
Location Name: Craig 1, 3
Location ID: 325351



Inspection Photos
Location Name: Craig 1, 3
Location ID: 325351

5/24/24
+37.194048,-107.834526
74° E



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 7. Reference area is an irrigated grass field comprised predominantly of smooth brome.

API #: 067-06223, 09732