

Inspection Photos

API: 071-08234

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 5/28/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south along the pre-existing access road. This area has washed out and needs to be repaired.



Inspection Photos



Photo 2. Facing southwest along the access road.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. Facing back northeast down the road. Stormwater from the location is directed down the roadside with insufficient BMP's. There is a rock check dam at red arrow that has filled in with sediment.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-08234 | Date: 5/28/2024

Inspection Photos



Photo 4. Facing southwest toward the location. The road continues on past the location however there is a culvert at red arrow that has washed out.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 5. Facing south toward the location. There are areas of the location that are covered with Field bindweed (noxious weed) that will need to be controlled.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 6. Facing southwest. The berms along the slope have filled in and eroded



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 7. There are several areas where erosion has occurred along the slope where berms have concentrated stormwater flow..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 8. South side of the location facing west The vegetation in this area is predominately Field bindweed which must be controlled. There is also erosion along this area that will need to be repaired.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-08234 | Date: 5/28/2024

Inspection Photos



Photo 9. South side of the location facing north.



Inspection Photos



Photo 10. Facing northwest toward the upper portion of the location. The perennial vegetation in this area is progressing well.



Inspection Photos



Photo 11. Facing southwest toward the upper portion of the location. The perennial vegetation in this area is progressing well.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 12. Northside of the location facing southwest. The lower portion of the location is not progressing and there are areas of weeds and erosion.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 13. Facing south toward the lower portion of the location. The large berms are filled in with sediment and are increasing the steepness of the slope toward the bottom. Regrading the lower portion of the location may be beneficial as the vegetation is not progressing.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-08234 | Date: 5/28/2024