

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/28/2024

Submitted Date:

05/28/2024

Document Number:

695109546

FIELD INSPECTION FORM

Loc ID 311922 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10705
 Name of Operator: EVERGREEN NATURAL RESOURCES LLC
 Address: 1875 LAWRENCE ST STE 1150
 City: DENVER State: CO Zip: 80202

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286044	WELL	SI	03/01/2017	CBM	071-08902	Dunn 14-5V	SI
286054	WELL	PR	08/08/2006	CBM	071-08892	Dunn 14-5R	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Prime Mover

1

Comment: R WELL

Corrective Action:

Date:

Type: Progressive Cavity

1

Comment: R WELL

Corrective Action:

Date:

Type: Vertical Separator

1

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked

6

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

2

Comment: BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Compressor

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

2

Comment: BOTH ARE ACCESSABLE

Corrective Action:

Date:

Type: Ancillary equipment

2

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 286044 Type: WELL API Number: 071-08902 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: THIS WELL IS INCORRECTLY BEING REPORTED AS SHUT IN, WELL IS TEMPORARY ABANDON

Corrective Action: Submit Form 4 as directed by Rule 434.b. THIS IS THE SECOND NOTICE Date: 02/05/2022

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 286054 Type: WELL API Number: 071-08892 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 08/07/2009 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: --

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 287218 Lat: 37.196314 Long: -104.916346

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date: _____

Type: Produced Water Lined: NO Pit ID: 287903 Lat: 37.196440 Long: -104.916580

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: <u>NO</u>	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>	
Comment:		Date:	
Corrective Action:			
Permit:	Facility ID	Permit Num	Expiration Date
	287218	1396168	
	287218	403427047	
	287903	1396368	

ECMC Comments		
Comment	User	Date
THIS IS A FOLLOW UP TO INSP DOC #695105436 CA HAS NOT BEEN ADDRESSED IMMEDIATE ACTION IS REQUIRED. THIS IS THE SECOND NOTICE FOR THIS CA.	beardslt	05/28/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403805739	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6565989
695109547	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6565444