



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	NOTIFIED OPERATOR BY PHONE THAT WEEDS AROUND LOCATION EQUIPMENT NEEDS TO BE MAINTAINED AT ALL TIMES.		
Corrective Action:			Date:
Type	OTHER		
Comment:	NOTIFIES OPERATOR BY PHONE TO CLEAN IMPACTED SOIL AROUND WELLHEAD		
Corrective Action:			Date:

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type				corrective date
Type: Ancillary equipment	# 2			
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:	ELECTRIC DRIVE			
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	IS ACCESSABLE			
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.			
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 256883 Type: WELL API Number: 071-06957 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 10/04/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695109530	INSP. PHOTOS	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6565436">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6565436</a>