

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/15/2024

Submitted Date:

05/15/2024

Document Number:

695109531

FIELD INSPECTION FORMLoc ID 307938 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: **Operator Information:**

ECMC Operator Number: 10351

Name of Operator: WAPITI OPERATING LLC

Address: 1251 LUMPKIN RD

City: HOUSTON State: TX Zip: 77043

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------------|---------------------------|-------------------------------|---------------------------|
| Madison, Randy | 575-445-6706/575-420-1120 | rmadison@wapitienergy.com | EHS Specialist |
| Mattorano, Michael | 575-445-6704/505-652-0416 | mmattorano@wapitienergy.com | Production superintendent |
| Middlebrook, Sonny | 575-445-6724/575-445-8610 | smiddlebrook@wapitienergy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 259792 | WELL | PR | 10/10/2001 | CBM | 071-07277 | VPR C 86 | PR |

General Comment:

| | | | | | |
|--|------|---|--|-----------------|--|
| Location | | | | | |
| Overall Good: <input checked="" type="checkbox"/> | | | | | |
| Emergency Contact Number: | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: _____ | |
| Overall Good: <input checked="" type="checkbox"/> | | | | | |
| Spills: | | | | | |
| Type | Area | Volume | | | |
| In Containment: No | | | | | |
| Comment: | | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | | |
| Equipment: | | | | corrective date | |
| Type: Pump Jack | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Type: Ancillary equipment | # 2 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Type: Deadman # & Marked | # 4 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Type: Gas Meter Run | # 1 | | | | |
| Comment: | | CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR. | | | |
| Corrective Action: | | | | Date: | |
| Type: Bradenhead | # 1 | | | | |
| Comment: | | IS ACCESSABLE | | | |
| Corrective Action: | | | | Date: | |
| Venting: | | | | | |
| Yes/No | NO | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Flaring: | | | | | |
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| | | | | | |

| Inspected Facilities | | | | | | | | | |
|-------------------------|----------------------------|------------------------|-------------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 259792 | Type: | WELL | API Number: | 071-07277 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |
| BradenHead | | | | | | | | | |
| Date of Last Brhd Test: | 10/24/2023 | Annual Brhd Completed? | Yes | | | | | | |
| Last Brhd Test Results | Initial Surf Csg Pressure: | 0 | Fluid Type: | | | | | | |
| | End Surf Csg Pressure: | 0 | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Compaction | Pass | Compaction | Pass | | | |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| | | |
|--------------|--------------|---|
| Document Num | Description | URL |
| 695109532 | INSP. PHOTOS | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6565437 |