

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/20/2024

Submitted Date:

05/22/2024

Document Number:

699700378

FIELD INSPECTION FORM

Loc ID 334957 Inspector Name: Heil, John On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210883	WELL	PR	05/23/1997	CBM	045-06641	EXXON GV 42-6	EI
210950	WELL	SI	10/01/2023	GW	045-06708	EXXON TW 11-6	EI
274468	WELL	PR	05/06/2005	GW	045-13354	PA 332-6	EI
274469	WELL	PR	10/29/2004	GW	045-13355	PA 432-6	EI
274470	WELL	PR	05/02/2005	GW	045-13356	PA 532-6	EI

General Comment:

[ECMC Environmental Inspection.](#)

Inspected Facilities

Facility ID: 210883 Type: WELL API Number: 045-06641 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 210950 Type: WELL API Number: 045-06708 Status: SI Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 274468 Type: WELL API Number: 045-13354 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 274469 Type: WELL API Number: 045-13355 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 274470 Type: WELL API Number: 045-13356 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Erosion rills present south of the wellheads adjacent to the access road.](#)

Corrective Action: **Comply with Rule 1002.f.(2)- Install or repair required stormwater and erosion control BMPs to properly divert stormwater runoff, and well as to stabilize the working pad surface, and to minimize tracking and off-site sediment transport.**

Ensure BMPs are installed in accordance with good engineering practices and maintained in a proper functioning condition; ongoing stormwater management required until Location receives a passing final reclamation inspection.

Date: 05/27/2024

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403800874	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6558507
699700379	20240520 Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6558502