

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/22/2024

Submitted Date:

05/28/2024

Document Number:

708903906

**FIELD INSPECTION FORM**

Loc ID 335288 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

18 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211258	WELL	PR	01/14/1996	GW	045-07017	CLOUGH RMV 57-20	PR
270308	WELL	PR	08/10/2004	GW	045-09522	CLOUGH RWF 412-20	PR
270309	WELL	PR	05/27/2004	GW	045-09523	CLOUGH RWF 512-20	PR

**General Comment:**

[CECMC Inspection Report Summary](#)  
On 05/22/2024 at approximately 12:34 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC CLOUGH RMV 57-20 pad. Location # 335288 in Garfield County Colorado. Location is within High Priority/Density Habitat areas. Location is approximately 32 yards from a creek/drainage that contributes to the Colorado River. While there, I observed normal production operations.

This is a summary of inspection report.

Remote location/Split pad - Wellheads only, production equipment is located on the CLOUGH 136 pad location # 322444

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	2 of the 3 wellhead signs are weathered & cracking		
Corrective Action:			Date:
Type	BATTERY		
Comment:	No tank battery on location		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead	# 3		corrective date
Comment:	RWF 512-20 well bradenhead equiped with Taylor plug, bradenhead valve is accessible.  No form of pressure monitoring equipment located on the other 2 bradenheads, bradenhead valves are accessible.		
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:	All wells on plunger lift		
Corrective Action:			Date:

Type: Deadman # & Marked	# 1		
Comment:	Marked		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 211258 Type: WELL API Number: 045-07017 Status: PR Insp. Status: PR

**Producing Well**

Comment:	Producing, well on plunger lift	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 270308 Type: WELL API Number: 045-09522 Status: PR Insp. Status: PR

**Producing Well**

Comment:	Producing, well on plunger lift	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 270309 Type: WELL API Number: 045-09523 Status: PR Insp. Status: PR

**Producing Well**

Comment:	Producing, well on plunger lift	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse to none
		Compaction				Some areas with light compaction
Compaction						Light compaction
Gravel						Sparse to none in most areas

Comment: Places with sparse to no gravel & light compaction are present on location. Sparse/no gravel and light compaction could lead to future stabilization and tracking issues.

No other observed BMP's

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<span style="color: blue;">Remote location/Split pad - Wellheads only, production equipment is located on the CLOUGH 136 pad location # 322444</span>	smelserw	05/28/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708903907	Inspection 708903906 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6565480">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6565480</a>
708903908	Inspection 708903906 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6565481">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6565481</a>