

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/22/2024

Submitted Date:

05/22/2024

Document Number:

699505831

FIELD INSPECTION FORM

| | | | | |
|---|-----------------------------------|---|-------------------|---|
| Loc ID 456747 | Inspector Name: MEDINA, JUSTIN | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED |
| Operator Information: ECMC Operator Number: 10459 Name of Operator: EXTRACTION OIL & GAS INC Address: 555 17TH STREET SUITE 3700 City: DENVER State: CO Zip: 80202 | | | | Findings: 3 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested |
| | | | | ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE |

| Contact Information: | | | |
|-----------------------------|-------|-------------------------------|---------|
| Contact Name | Phone | Email | Comment |
| , | | Inspections@civiresources.com | |

| Inspected Facilities: | | | | | | | |
|------------------------------|------|--------|-------------|------------|-----------|--------------------------|-------------|
| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
| 456737 | WELL | PR | 09/05/2022 | OW | 014-20760 | INTERCHANGE A S22-30-10C | PR |
| 456740 | WELL | PR | 09/05/2022 | OW | 014-20763 | INTERCHANGE A S22-30-5N | PR |
| 456742 | WELL | PR | 09/05/2022 | OW | 014-20765 | INTERCHANGE A S22-30-12N | PR |
| 456743 | WELL | PR | 09/05/2022 | OW | 014-20766 | INTERCHANGE A S22-30-8N | PR |
| 456744 | WELL | PR | 09/05/2022 | OW | 014-20767 | INTERCHANGE A S22-30-3N | PR |
| 456745 | WELL | PR | 09/05/2022 | OW | 014-20768 | INTERCHANGE A S22-30-7C | PR |
| 456749 | WELL | PR | 09/05/2022 | OW | 014-20771 | INTERCHANGE A S22-30-9N | PR |
| 456752 | WELL | PR | 10/13/2019 | OW | 014-20772 | Interchange B N35-20-5C | PR |
| 456753 | WELL | PR | 10/13/2019 | OW | 014-20773 | Interchange B N35-20-9N | PR |
| 456754 | WELL | PR | 08/01/2022 | OW | 014-20774 | Interchange B N35-20-4N | PR |
| 456755 | WELL | PR | 10/13/2019 | OW | 014-20775 | Interchange B N35-20-7N | PR |
| 456756 | WELL | PR | 10/13/2019 | OW | 014-20776 | Interchange B N35-20-8C | PR |
| 456757 | WELL | PR | 10/13/2019 | OW | 014-20777 | Interchange B N35-20-6N | PR |
| 456758 | WELL | PR | 11/01/2022 | OW | 014-20778 | INTERCHANGE B S22-30-19C | PR |
| 456759 | WELL | PR | 01/01/2024 | OW | 014-20779 | INTERCHANGE B S22-30-14N | PR |
| 456760 | WELL | PR | 03/01/2024 | OW | 014-20780 | INTERCHANGE B S22-30-15N | PR |

| | | | | | | | |
|--------|------|----|------------|----|-----------|--------------------------|----|
| 456761 | WELL | PR | 11/01/2022 | OW | 014-20781 | INTERCHANGE B S22-30-18N | PR |
| 456763 | WELL | PR | 11/01/2022 | OW | 014-20783 | INTERCHANGE B S22-30-16C | PR |
| 463341 | WELL | PR | 10/13/2019 | OW | 014-20843 | Interchange B N35-20-3N | PR |
| 463342 | WELL | PR | 10/13/2019 | OW | 014-20844 | Interchange B N35-20-10N | PR |
| 463343 | WELL | PR | 10/13/2019 | OW | 014-20845 | Interchange B N35-20-1N | PR |
| 463344 | WELL | PR | 10/13/2019 | OW | 014-20846 | Interchange B N35-20-2C | PR |
| 468826 | WELL | PR | 09/05/2022 | OW | 014-20849 | INTERCHANGE A S16-20-20N | PR |
| 468827 | WELL | PR | 09/05/2022 | OW | 014-20850 | INTERCHANGE A S22-30-1C | PR |
| 468828 | WELL | PR | 11/01/2022 | OW | 014-20851 | INTERCHANGE B S22-30-20N | PR |
| 468829 | WELL | PR | 09/05/2022 | OW | 014-20852 | INTERCHANGE A S22-30-21N | PR |

General Comment:

There have been no changes to equipment on location since previous inspection.

| | | | | | |
|--|------|--------|-------|--|-------------|
| Location | | | | | |
| Overall Good: <input checked="" type="checkbox"/> | | | | | |
| Emergency Contact Number: | | | | | |
| Comment: | | | | | Date: _____ |
| Corrective Action: | | | | | |
| Overall Good: <input checked="" type="checkbox"/> | | | | | |
| Spills: | | | | | |
| Type | Area | Volume | | | |
| In Containment: No | | | | | |
| Comment: | | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | | |
| Venting: | | | | | |
| Yes/No | NO | | | | |
| Comment: | | | | | |
| Corrective Action: | | | Date: | | |
| Flaring: | | | | | |
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | Date: | | |

| Inspected Facilities | | | | | | | | | |
|--|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 456737 | Type: | WELL | API Number: | 014-20760 | Status: | PR | Insp. Status: | PR |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | |
| Facility ID: | 456740 | Type: | WELL | API Number: | 014-20763 | Status: | PR | Insp. Status: | PR |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | |
| Facility ID: | 456742 | Type: | WELL | API Number: | 014-20765 | Status: | PR | Insp. Status: | PR |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | |
| Facility ID: | 456743 | Type: | WELL | API Number: | 014-20766 | Status: | PR | Insp. Status: | PR |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | |
| Facility ID: | 456744 | Type: | WELL | API Number: | 014-20767 | Status: | PR | Insp. Status: | PR |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | |
| Facility ID: | 456745 | Type: | WELL | API Number: | 014-20768 | Status: | PR | Insp. Status: | PR |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | |
| Facility ID: | 456749 | Type: | WELL | API Number: | 014-20771 | Status: | PR | Insp. Status: | PR |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | |
| Facility ID: | 456752 | Type: | WELL | API Number: | 014-20772 | Status: | PR | Insp. Status: | PR |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | |
| Facility ID: | 456753 | Type: | WELL | API Number: | 014-20773 | Status: | PR | Insp. Status: | PR |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | |
| Facility ID: | 456754 | Type: | WELL | API Number: | 014-20774 | Status: | PR | Insp. Status: | PR |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | |
| Facility ID: | 456755 | Type: | WELL | API Number: | 014-20775 | Status: | PR | Insp. Status: | PR |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | |
| Facility ID: | 456756 | Type: | WELL | API Number: | 014-20776 | Status: | PR | Insp. Status: | PR |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | |
| Facility ID: | 456757 | Type: | WELL | API Number: | 014-20777 | Status: | PR | Insp. Status: | PR |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | |
| Facility ID: | 456758 | Type: | WELL | API Number: | 014-20778 | Status: | PR | Insp. Status: | PR |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | |
| Facility ID: | 456759 | Type: | WELL | API Number: | 014-20779 | Status: | PR | Insp. Status: | PR |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | |
| Facility ID: | 456760 | Type: | WELL | API Number: | 014-20780 | Status: | PR | Insp. Status: | PR |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | |

Inspector Name: MEDINA, JUSTIN

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 456761 | Type: | WELL | API Number: | 014-20781 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 456763 | Type: | WELL | API Number: | 014-20783 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 463341 | Type: | WELL | API Number: | 014-20843 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 463342 | Type: | WELL | API Number: | 014-20844 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 463343 | Type: | WELL | API Number: | 014-20845 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 463344 | Type: | WELL | API Number: | 014-20846 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 468826 | Type: | WELL | API Number: | 014-20849 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 468827 | Type: | WELL | API Number: | 014-20850 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 468828 | Type: | WELL | API Number: | 014-20851 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 468829 | Type: | WELL | API Number: | 014-20852 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 12/05/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment

User

Date

At time of inspection location appears to be in compliance with ECMC rules.
At time of inspection weather conditions were warm, windy, clear.

medinaj

05/22/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 699505832 | Inspection pictures | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6566442 |