



FORM
INSP

Rev
X/20

State of Colorado
Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
05/24/2024
Submitted Date:
05/24/2024
Document Number:
699505850

Loc ID
318894

Inspector Name:
MEDINA, JUSTIN

On-Site Inspection ☐
2A Doc Num: _____

Operator Information:
ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Status Summary:
☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED
Findings:
4 Number of Comments
0 Number of Corrective Actions
☐ Corrective Action Response Requested
ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242405	WELL	PR	03/01/2024	GW	123-10196	YOXALL FARMS 10	PR
432048	WELL	PA	07/10/2013	DA	123-36927	HOWARD 2N-33HZ	PA
432049	WELL	PR	03/01/2023	OW	123-36928	HOWARD 27N-28HZ	PR
432050	WELL	PA	07/10/2013	DA	123-36929	HOWARD 28C-33HZ	PA
432052	WELL	PR	01/01/2024	OW	123-36931	HOWARD 27C-33HZ	PR
432053	WELL	PR	12/01/2022	OW	123-36932	HOWARD 28C-33HZR	PR
432054	WELL	PR	05/01/2021	OW	123-36933	HOWARD 1C-28HZ	PR
432055	WELL	PR	10/01/2022	OW	123-36934	HOWARD 26N-28HZ	PR
434180	WELL	PR	04/23/2014	OW	123-38006	HOWARD 2N-33HZR	PR

General Comment:

There have been no changes to equipment on location since previous inspection.

Date Run: 5/29/2024 Doc [#699505850]

Page 1 of 4

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:					Date: _____
Corrective Action:					
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:			Date:		
Flaring:					
Type					
Comment:					
Corrective Action:			Date:		

Inspected Facilities

Facility ID: 242405	Type: WELL	API Number: 123-10196	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 432048	Type: WELL	API Number: 123-36927	Status: PA	Insp. Status: PA
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 432049	Type: WELL	API Number: 123-36928	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 432050	Type: WELL	API Number: 123-36929	Status: PA	Insp. Status: PA
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 432052	Type: WELL	API Number: 123-36931	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 432053	Type: WELL	API Number: 123-36932	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 432054	Type: WELL	API Number: 123-36933	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 432055	Type: WELL	API Number: 123-36934	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 434180	Type: WELL	API Number: 123-38006	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/22/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment

User

Date

At time of inspection location appears to be in compliance with ECMC rules.
At time of inspection weather conditions were warm, windy, clear.

medinaj

05/24/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699505851	Inspection pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6566453