



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type WELLHEAD

Comment: [ag fencing & 6' chain link with barb wire](#)

Corrective Action:

Date: \_\_\_\_\_

**Equipment:**

corrective date

Type: Bradenhead # 1

Comment: [Plumbed to surface](#)

Corrective Action:

Date: \_\_\_\_\_

Type: Deadman # & Marked # 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Ancillary equipment # 1

Comment: [automation](#)

Corrective Action:

Date: \_\_\_\_\_

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Flaring:**

Type

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Inspected Facilities**

Facility ID: 201536 Type: WELL API Number: 001-06939 Status: AC Insp. Status: AC

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with ECMC rules. At time of inspection weather conditions were warm, sunny, calm.	medinaj	05/28/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699505867	inspection pictures	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6566463">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6566463</a>