

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/29/2024

Submitted Date:

05/29/2024

Document Number:

715200277

**FIELD INSPECTION FORM**Loc ID 321637 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 17180

Name of Operator: CITATION OIL &amp; GAS CORP

Address: 14077 CUTTEN RD

City: HOUSTON State: TX Zip: 77069

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

18 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	
Rogers, Bob	719-767-8851	brogers@cogc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207604	WELL	PR	09/07/1985	GW	017-06539	MPU 33-30 2	PR

**General Comment:**

Routine Inspection

**Location****Lease Road:**

Type	Access		
comment:	Partially elevated gravel road through pasture with a cattle guard at entrance		
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	Lease sign at tank battery		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tanks		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	Tank battery is 3/4 fenced with wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:		Date:	

**Equipment:**

Type: Prime Mover	# 1		corrective date
Comment:	Ford 300-6 cylinder engine		
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:	2-Vertical gas separators in east treater shed		
Corrective Action:		Date:	

Type: Pump Jack	# 1	
Comment:	C&W 228	
Corrective Action:		Date:
Type: LACT	# 1	
Comment:	LACT unit and telemetry equipment operated by Plains All American Pipeline	
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Vertical Heater Treater	# 2	
Comment:	2-Treaters w/metal shed	
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:	2-Meter runs on east side of water tank	
Corrective Action:		Date:
Type: Ancillary equipment	# 5	
Comment:	Cathodic rectifier, day drum, electric panel at tanks, 2-circ pumps at battery	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	FIBERGLASS AST		38.881140,-102.708230
Comment:	Water tank on east side of treaters				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	FIBERGLASS AST		38.881330,-102.708060
Comment:	Vent tank on north side of location				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	

Other (Capacity)																													
Other (Type)																													
<u>Berms</u>																													
Type				Capacity				Permeability (Wall)				Permeability (Base)				Maintenance													
Earth				Adequate				Walls Sufficent				Base Sufficent				Adequate													
Comment:																													
Corrective Action:																Date:													
Contents				#	Capacity			Type					Tank ID		SE GPS														
CRUDE OIL				6	300 BBLS			STEEL AST							38.881140,-102.707570														
Comment:				6-Production tanks on east side of tank battery location																									
Corrective Action:																Date:													
<u>Paint</u>																													
Condition																													
Other (Content)																													
Other (Capacity)																													
Other (Type)																													
<u>Berms</u>																													
Type				Capacity				Permeability (Wall)				Permeability (Base)				Maintenance													
Earth				Adequate				Walls Sufficent				Base Sufficent				Adequate													
Comment:																													
Corrective Action:																Date:													
<u>Wells Served By Facilities Above</u>																				<u>AirsID</u>									
API Number										API Number										AirsID									
017-06545																													
017-06539																													
<u>Venting:</u>																													
Yes/No																													
Comment:																													
Corrective Action:														Date:															
<u>Flaring:</u>																													
Type																													
Comment:																													
Corrective Action:														Date:															

Inspected Facilities									
Facility ID:	207604	Type:	WELL	API Number:	017-06539	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Central tank battery for (MPU 33-30 and 24-30) 2000' SE @ 38.881140/-102.707570								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715200280	location photo	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6566958">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6566958</a>