

WELL NAME: HILL RANCH 07-09, API #: 071-08065, INSP. # 695109588



PHOTO 1: WELL SIGN/ SIGN IS DETERIORATING AND NEEDS REPLACED.

WGS84
±16ft

37.01090, -104.92337

ft
±10ft

8253

°M
±17

SW204



PHOTO 2: WELLHEAD AND EQUIPMENT





PHOTO 3: AREA OF IMPACTED SOIL NEAR WELLHEAD.





PHOTO 4: ENGINE SKID AND SOUND WALLS ARE UNUSED EQUIPEMT AND SHOULD BE PUT BACK IN WORKING ORDER OR REMOVED FROM LOCATION.



PHOTO 5: NETTING IS TORN AND PART OF IT IS BELOW WATER. REPAIR NETTING.



PHOTO 6: FENCING AROUND LINED PIT IS DOWN. REPAIR FENCE.