

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/29/2024

Submitted Date:

05/29/2024

Document Number:

713300951

**FIELD INSPECTION FORM**

Loc ID: 318502    Inspector Name: Kester, Michael    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER    State: CO    Zip: 80203

**Findings:**

10 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Silver, Randy	720-827-6688	randy.silver@state.co.us	
, KPK	303-825-4822	cogcc@kpk.com	<a href="#">all inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241423	WELL	SI	04/01/2023	GW	123-09212	UPRR 42 PAN AM AN 1	SI

**General Comment:**

[Follow up inspection](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	safety guards		
Corrective Action:		Date:	
Type	OTHER		
Comment:	electric disconnect, metal panel		
Corrective Action:		Date:	

**Equipment:**

Type	Equipment ID	Comment	Corrective Action	Date	corrective date
Pump Jack	# 1				
		Comment:			
		Corrective Action:		Date:	
Ancillary equipment	# 3				
		Comment:	electric disconnect panels		
		Corrective Action:		Date:	
Bradenhead	# 1				
		Comment:	piped to surface		
		Corrective Action:		Date:	
Prime Mover	# 1				
		Comment:	electric		
		Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 241423 Type: WELL API Number: 123-09212 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Valves appeared to be closed at time of inspection

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 08/02/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><b>ECMC Inspection Report Summary</b>                      Inspector Michael Kester,                      conducted on-site inspection                      Location: UPRR 42 PanAm AN-1                      Operator: KPK                      API#: 123-09212                      County: Weld</p> <p>While there, I observed well site with pumping unit,</p> <p>Follow up inspection as per Doc # 699505006, corrective actions appeared to have been addressed</p> <p>Weather conditions: sunny and dry</p> <p>This inspection does not nullify any orders or NOAV from the ECMC                      This is a continuing education inspection</p>	kesterm	05/29/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300952	site pic	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6567297">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6567297</a>