

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/29/2024

Submitted Date:

05/29/2024

Document Number:

714201068

FIELD INSPECTION FORM

Loc ID 429360 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 15 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429367	WELL	PR	11/01/2019	OW	123-35786	CANNON 36N-W3HZX	PR
429368	WELL	PR	02/01/2020	GW	123-35787	CANNON 15N-W3HZ	PR
429370	WELL	PR	11/01/2019	OW	123-35789	CANNON 36N-E3HZ	PR
429372	WELL	PR	11/01/2019	OW	123-35791	CANNON 14N-E3HZ	PR

General Comment:

[THIS IS A WELLHEAD/BATTERY INSPECTION](#)

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:	Debris at battery. see attached photos		
Corrective Action:	Comply with Rule 606	Date:	06/12/2024

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	panel		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	wire		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 4		corrective date
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: LACT	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 4		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	210 BBLs	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment: Shares containment with other tanks.					
Corrective Action:				Date:	
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 429367 Type: WELL API Number: 123-35786 Status: PR Insp. Status: PR

Producing Well

Comment: PR; valves appear to be in the open position.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 05/30/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 40 Fluid Type: WATER H2O
 End Surf Csg Pressure: 1

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 429368 Type: WELL API Number: 123-35787 Status: PR Insp. Status: PR

Producing Well

Comment: PR; valves appear to be in the open position.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 09/21/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None
 End Surf Csg Pressure: --

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 429370 Type: WELL API Number: 123-35789 Status: PR Insp. Status: PR

Producing Well

Comment: PR; valves appear to be in the open position.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 04/29/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 39 Fluid Type: WATER H2O
 End Surf Csg Pressure: 1

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 429372 Type: WELL API Number: 123-35791 Status: PR Insp. Status: PR

Producing Well

Comment: PR; valves appear to be in the open position.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 09/20/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 25 Fluid Type: Water

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary WEATHER CONDITIONS: sunny, dry ground. On Wednesday, May 29, 2024 at approximately 1515, I, Inspector Brittani Santistevan, conducted an on-site inspection at CANNON 14N-E3HZ,36N-W3HZX, 36N-E3HZ, 15N-W3HZ (Kerr McGee Oil & Gas Onshore), at location ID: 429360 in WELD COUNTY, Colorado. While there, I observed a producing facility. During this inspection the following possible compliance issues were observed: 1. It appears to be debris near tank battery. Comply with Rule 606. (Corrective Action Date: June 12, 2024) See attached photo #6, 7.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	05/29/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714201069	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6568299