

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/30/2024

Submitted Date:

05/30/2024

Document Number:

714201070

FIELD INSPECTION FORMLoc ID 438862 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

33 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438861	WELL	PR	06/01/2023	OW	123-40167	SUMMIT 34C-32HZ	PR
438863	WELL	PR	12/01/2022	OW	123-40168	SUMMIT 3N-29HZ	PR
438864	WELL	PR	12/01/2022	OW	123-40169	SUMMIT 28C-29HZ	PR
438865	WELL	PR	12/01/2022	OW	123-40170	SUMMIT 14C-32HZ	PR
438866	WELL	PR	12/01/2022	OW	123-40171	SUMMIT 13C-32HZ	PR
438867	WELL	PR	12/01/2022	OW	123-40172	SUMMIT 3C-29HZ	PR
438868	WELL	PR	06/01/2023	OW	123-40173	SUMMIT 4C-29HZ	PR
438869	WELL	PR	12/01/2022	OW	123-40174	SUMMIT 36C-32HZ	PR
438870	WELL	PR	07/01/2023	OW	123-40175	SUMMIT 29N-29HZ	PR
438871	WELL	PR	06/01/2023	OW	123-40176	SUMMIT 13N-32HZ	PR
438873	WELL	PR	12/01/2022	OW	123-40178	SUMMIT 36N-32HZ	PR
438874	WELL	PR	07/01/2023	OW	123-40179	SUMMIT 35N-32HZ	PR

General Comment:

THIS IS A WELLHEAD/BATTERY INSPECTION

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	iron		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	iron		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 12		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 12		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		

Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: LACT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 13		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 12		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	210 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with other tanks.				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities			
Facility ID: 438861	Type: WELL	API Number: 123-40167	Status: PR Insp. Status: PR
Producing Well			
Comment: PR; it appears valves are in the open position.			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: 02/17/2023		Annual Brhd Completed? No	
Last Brhd Test Results		Initial Surf Csg Pressure: 10 Fluid Type: None	
End Surf Csg Pressure: --			
Comment: SUBMIT REPORT			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 438863	Type: WELL	API Number: 123-40168	Status: PR Insp. Status: PR
Producing Well			
Comment: PR; it appears valves are in the open position.			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: 02/17/2023		Annual Brhd Completed? No	
Last Brhd Test Results		Initial Surf Csg Pressure: 16 Fluid Type: None	
End Surf Csg Pressure: --			
Comment: SUBMIT REPORT			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 438864	Type: WELL	API Number: 123-40169	Status: PR Insp. Status: PR
Producing Well			
Comment: PR; it appears valves are in the open position.			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: 12/15/2023		Annual Brhd Completed? No	
Last Brhd Test Results		Initial Surf Csg Pressure: 0 Fluid Type: NONE	
End Surf Csg Pressure: 0			
Comment: SUBMIT REPORT			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 438865	Type: WELL	API Number: 123-40170	Status: PR Insp. Status: PR
Producing Well			
Comment: PR; it appears valves are in the open position.			
Corrective Action:		Date:	

BradenHead

Date of Last Brhd Test: 02/20/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 27 Fluid Type: None

End Surf Csg Pressure: --

Comment: SUBMIT REPORT

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 438866 Type: WELL API Number: 123-40171 Status: PR Insp. Status: PR

Producing Well

Comment: PR; it appears valves are in the open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/17/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: None

End Surf Csg Pressure: --

Comment: SUBMIT REPORT

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 438867 Type: WELL API Number: 123-40172 Status: PR Insp. Status: PR

Producing Well

Comment: PR; it appears valves are in the open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/17/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: None

End Surf Csg Pressure: --

Comment: SUBMIT REPORT

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 438868 Type: WELL API Number: 123-40173 Status: PR Insp. Status: PR

Producing Well

Comment: PR; it appears valves are in the open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/21/2024 Annual Brhd Completed? Yes
Last Brhd Test Results Initial Surf Csg Pressure: 46 Fluid Type: WATER H2O
End Surf Csg Pressure: 0

Comment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 438869 Type: WELL API Number: 123-40174 Status: PR Insp. Status: PR

Producing Well

Comment: PR; it appears valves are in the open position.

Corrective Action: Date: **BradenHead**

Date of Last Brhd Test: 02/20/2023 Annual Brhd Completed? No
Last Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type: None
End Surf Csg Pressure: --

Comment: SUBMIT REPORT

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 438870 Type: WELL API Number: 123-40175 Status: PR Insp. Status: PR

Producing Well

Comment: PR; it appears valves are in the open position.

Corrective Action: Date: **BradenHead**

Date of Last Brhd Test: 02/17/2023 Annual Brhd Completed? No
Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None
End Surf Csg Pressure: --

Comment: SUBMIT REPORT

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 438871 Type: WELL API Number: 123-40176 Status: PR Insp. Status: PR

Producing Well

Comment: PR; it appears valves are in the open position.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 02/17/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment: SUBMIT REPORT

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 438873 Type: WELL API Number: 123-40178 Status: PR Insp. Status: PR

Producing Well

Comment: PR; it appears valves are in the open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/20/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 18 Fluid Type: None

End Surf Csg Pressure: --

Comment: SUBMIT REPORT

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 438874 Type: WELL API Number: 123-40179 Status: PR Insp. Status: PR

Producing Well

Comment: PR; it appears valves are in the open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/17/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment: SUBMIT REPORT

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Routine Inspection. Weather Conditions: sunny, dry ground.	santistb	05/30/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714201071	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6568300