

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/29/2024

Submitted Date:

05/30/2024

Document Number:

707602881

FIELD INSPECTION FORM

Loc ID 330621 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 69175
 Name of Operator: PDC ENERGY INC
 Address: 1099 18TH STREET SUITE 1500
 City: DENVER State: CO Zip: 80202

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251564	WELL	PA	11/10/2017	OW	123-19367	LOUSTALET 21-15	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL / ABANDONED BATTERY** inspection.
 Well(s): 1: Plugged & Abandoned | PA.
 Battery: Abandoned. ALL equipment has been removed.
 Abandoned Battery SE corner GPS coordinates: 40.46750 / -104.537900

 Abandoned Centralized Battery formerly served 2 Location IDs (330621, 331362).
 (Well(s): 2: Plugged & Abandoned | PA).

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume			corrective date
Type: Plunger Lift	# 0				
Comment:	Plugged & Abandoned PA. Equipment removed.				
Corrective Action:					Date:
Type: Emission Control Device	# 0				
Comment:	Plugged & Abandoned PA. Battery Abandoned. Equipment removed.				
Corrective Action:					Date:
Type: Gas Meter Run	# 0				
Comment:	Plugged & Abandoned PA. Battery Abandoned. Equipment removed.				
Corrective Action:					Date:
Type: Horizontal Heated Separator	# 0				
Comment:	Plugged & Abandoned PA. Battery Abandoned. Equipment removed.				
Corrective Action:					Date:
Type: Ancillary equipment	# 0				
Comment:	Plugged & Abandoned PA. Battery Abandoned. Equipment removed.				
Corrective Action:					Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:	Plugged & Abandoned PA. Battery Abandoned. Equipment removed.				
Corrective Action:					Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0					
Comment: Plugged & Abandoned PA. Battery Abandoned. Equipment removed.						
Corrective Action:				Date:		

Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		

Venting:						
Yes/No						
Comment:						
Corrective Action:					Date:	

Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected FacilitiesFacility ID: 251564 Type: WELL API Number: 123-19367 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On WED 05/29/2024 at approximately 12:24 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: PDC ENERGY INC Location Name: LOUSTALET-65N64W/15NENW Location ID: 330621 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.46750 / -104.537900</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Form 6-SRA on file. Plugging, cut/cap date: 11/10/2017. Approved. Plugged & Abandoned PA well GPS coordinates: 40.405250 / -104.537940</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	05/30/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602882	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6568468