

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/29/2024

Submitted Date:

05/30/2024

Document Number:

707602883

**FIELD INSPECTION FORM**

Loc ID 323125	Inspector Name: Evins, Bret	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 30 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> ECMC Operator Number: 69175 Name of Operator: PDC ENERGY INC Address: 1099 18TH STREET SUITE 1500 City: DENVER State: CO Zip: 80202				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447729	WELL	PR	10/01/2023	OW	123-43559	Wacker 10G-212	PR
447730	WELL	PR	10/01/2023	OW	123-43560	Wacker 10G-302	PR
447731	WELL	PR	10/01/2023	OW	123-43561	Wacker 10F-232	PR
447732	WELL	SI	02/01/2024	OW	123-43562	Wacker 10G-304	PR
447733	WELL	PR	10/01/2023	OW	123-43563	Wacker 10F-304	PR
447734	WELL	PR	10/01/2023	OW	123-43564	Wacker 10F-302	PR
447735	WELL	PR	10/01/2023	OW	123-43565	Wacker 10F-234	PR
447736	WELL	PR	10/01/2023	OW	123-43566	Wacker 10G-312	PR
447737	WELL	PR	10/01/2023	OW	123-43567	Wacker 10F-204	PR
447738	WELL	PR	10/01/2023	OW	123-43568	Wacker 10G-214	PR
447739	WELL	PR	10/01/2023	OW	123-43569	Wacker 10G-314	PR

<b>General Comment:</b>  This is a WELL inspection. Well(s): 11: Producing   PR. Battery: Active.  Centralized Battery serves 1 Location ID (323125). (Well(s): 11: Producing   PR).  Centralized Battery serves 1 Tank Battery Facility ID (Pending).  Reference (Associated Well(s), Battery Inspections): A.) Field Inspection Report doc. #707602883 and/or Location ID #323125 for PR Well(s) info. B.) Field Inspection Report doc. #707602885 and/or Location ID #459972 for Battery / Facility, Equipment info.
--

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	11: Wellsite(s).		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	11: Wellsite(s). Iron panel.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Wellsite(s): Solar Power bank.		
Corrective Action:		Date:	
Type: Bradenhead	# 11		
Comment:	11: Wellsite(s). Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Other	# 11		
Comment:	11: Wellsite(s). Gas lift injection line(s).		
Corrective Action:		Date:	
Type: Gas Meter Run	# 11		
Comment:	Wellsite(s): 11: Gas Lift Allocation meter(s) (PDC). Calibration card(s): Sealed, automated. Last calibration: Sealed, automated.		
Corrective Action:		Date:	

Type: Plunger Lift	# 11	
Comment: 11: Wellsite(s).		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.416620,-104.541918
Comment:	Centralized Battery serves 1 Location ID (323125). (Well(s): 11: Producing   PR).  Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities			
Facility ID: 447729	Type: WELL	API Number: 123-43559	Status: PR    Insp. Status: PR
<b>Producing Well</b>			
Comment: <a href="#">Producing   PR.</a>			
Corrective Action:		Date:	
<b>BradenHead</b>			
Date of Last Brhd Test: 05/23/2023		Annual Brhd Completed? No	
Last Brhd Test Results		Initial Surf Csg Pressure: 0    Fluid Type:	
End Surf Csg Pressure: 0			
Comment: <a href="#">Record of last Brhd test &gt; 12 months. Refer to Rule 207. Submit current Brhd test. Comply w/ Rule 207.</a>			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 447730	Type: WELL	API Number: 123-43560	Status: PR    Insp. Status: PR
<b>Producing Well</b>			
Comment: <a href="#">Producing   PR.</a>			
Corrective Action:		Date:	
<b>BradenHead</b>			
Date of Last Brhd Test: 07/24/2023		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 5    Fluid Type: WATER AND GAS	
End Surf Csg Pressure: 0			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 447731	Type: WELL	API Number: 123-43561	Status: PR    Insp. Status: PR
<b>Producing Well</b>			
Comment: <a href="#">Producing   PR.</a>			
Corrective Action:		Date:	
<b>BradenHead</b>			
Date of Last Brhd Test: 05/23/2023		Annual Brhd Completed?	
Last Brhd Test Results		Initial Surf Csg Pressure: 8    Fluid Type:	
End Surf Csg Pressure: 0			
Comment: <a href="#">Record of last Brhd test &gt; 12 months. Refer to Rule 207. Submit current Brhd test. Comply w/ Rule 207.</a>			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 447732	Type: WELL	API Number: 123-43562	Status: SI    Insp. Status: PR
<b>Producing Well</b>			
Comment: <a href="#">Producing   PR.</a>			

Corrective Action:		Date:	
<b>BradenHead</b>			
Date of Last Brhd Test:	05/09/2024	Annual Brhd Completed?	Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 286	Fluid Type:	GAS AND LIQUID HYDROCARBON
	End Surf Csg Pressure: 0		
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 447733 Type: WELL API Number: 123-43563 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:	Producing   PR.		
Corrective Action:		Date:	

<b>BradenHead</b>			
Date of Last Brhd Test:	05/23/2023	Annual Brhd Completed?	No
Last Brhd Test Results	Initial Surf Csg Pressure: 0	Fluid Type:	
	End Surf Csg Pressure: 0		
Comment:	Record of last Brhd test > 12 months. Refer to Rule 207. Submit current Brhd test. Comply w/ Rule 207.		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 447734 Type: WELL API Number: 123-43564 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:	Producing   PR.		
Corrective Action:		Date:	

<b>BradenHead</b>			
Date of Last Brhd Test:	05/09/2024	Annual Brhd Completed?	Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 59	Fluid Type:	GAS
	End Surf Csg Pressure: 0		
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 447735 Type: WELL API Number: 123-43565 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:	Producing   PR.		
Corrective Action:		Date:	

**BradenHead**

Date of Last Brhd Test: 05/23/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment: Record of last Brhd test > 12 months. Refer to Rule 207.  
Submit current Brhd test. Comply w/ Rule 207.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 447736 Type: WELL API Number: 123-43566 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing | PR.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 05/23/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 7 Fluid Type:

End Surf Csg Pressure: 0

Comment: Record of last Brhd test > 12 months. Refer to Rule 207.  
Submit current Brhd test. Comply w/ Rule 207.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 447737 Type: WELL API Number: 123-43567 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing | PR.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 01/02/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: GAS

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 447738 Type: WELL API Number: 123-43568 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing | PR.

Corrective Action:

Date:

<b>BradenHead</b>			
Date of Last Brhd Test: 05/23/2023		Annual Brhd Completed? No	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment:		Record of last Brhd test > 12 months. Refer to Rule 207. Submit current Brhd test. Comply w/ Rule 207.	
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 447739	Type: WELL	API Number: 123-43569	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

<b>Producing Well</b>			
Comment:		Producing   PR.	
Corrective Action:		Date:	

<b>BradenHead</b>			
Date of Last Brhd Test: 05/23/2023		Annual Brhd Completed? No	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment:		Record of last Brhd test > 12 months. Refer to Rule 207. Submit current Brhd test. Comply w/ Rule 207.	
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On WED 05/29/2024 at approximately 12:49 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: PDC ENERGY INC Location Name: Wacker/5N64W10G Location ID: 323125 Well Name(s) &amp; API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 11: Producing   PR. Battery: Active.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	05/30/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602884	Site photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6568469">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6568469</a>