

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403807531

Date Received:

05/30/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 5 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10779

Name of Operator: SCOUT ENERGY MANAGEMENT LLC

Address: 13800 MONTFORT DRIVE SUITE 100

City: DALLAS State: TX Zip: 75240

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Patterson, Chris</u>		<u>Chris.Patterson@scoutep.com</u>
<u>Johnson, Mike</u>		<u>Mike.Johnson@scoutep.com</u>
<u>Sanford, Anita</u>	<u>(970) 551-8313</u>	<u>Anita.Sanford@scoutep.com</u>
<u>Regulatory, Rangely</u>		<u>RangelyRegulatory@scoutep.com</u>
<u>Wilson, Justin</u>	<u>(970) 878-3825</u>	<u>jrwilson@blm.gov</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 715500087

Inspection Date: 05/28/2024

FIR Submit Date: 05/28/2024

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: SCOUT ENERGY MANAGEMENT LLC

Company Number: 10779

Address: 13800 MONTFORT DRIVE SUITE 100

City: DALLAS State: TX Zip: 75240

LOCATION - Location ID: 315166

Location Name: HILL-61N101W Number: 6SWNE County: RIO BLANCO

Qtrqtr: SWNE Sec: 6 Twp: 1N Range: 101W Meridian: 6

Latitude: 40.086750 Longitude: -108.770970

FACILITY - API Number: 05-103- -00 Facility ID: 230357

Facility Name: HILL Number: 7-6

Qtrqtr: SWNE Sec: 6 Twp: 1N Range: 101W Meridian: 6

Latitude: 40.086750 Longitude: -108.770970

CORRECTIVE ACTIONS:

1 ☒ CA# 195441

Corrective Action: All load lines or tank valves that can be used as a load line will be capped or plugged.

Date: 06/03/2024

Response: CA COMPLETED

Date of Completion: 05/29/2024

Operator  
Comment:

Load line capped.

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

2 ☒ CA# 195442

Corrective Action: Remove and properly dispose of oily waste and impacted soil.

Date: 06/13/2024

Response: CA COMPLETED

Date of Completion: 05/29/2024

Operator  
Comment:

Removed and properly disposed of oily waste and impacted soil.

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

3 ☒ CA# 195443

Corrective Action: Remove and properly dispose of oily waste and impacted soil.

Date: 06/13/2024

Response: CA COMPLETED

Date of Completion: 05/29/2024

Operator  
Comment:

Removed and properly disposed of oily waste and impacted soil.

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

4 ☒ CA# 195444

Corrective Action: All excess materials, rubbish, supplies, trash, or other waste material will be properly contained until removed from the Oil and Gas Location. At no time will debris be placed or remain on the ground.

Date: 06/05/2024

Response: CA COMPLETED

Date of Completion: 05/29/2024

Operator  
Comment:

All excess materials, rubbish, supplies, trash, or other waste material were removed from the Oil and Gas Location. No debris remains on the ground.

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: NOTE item #195445 Sign was ordered and a FIRR CA will submitted as soon as installed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Anita Sanford

Signed: \_\_\_\_\_

Title: Sr. Regulatory Analyst

Date: 5/30/2024 7:43:17 AM

## ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403807531	FIR RESOLUTION SUBMITTED
403807553	Corrective Pictures of Location

Total Attach: 2 Files