

Final Reclamation and Stormwater Inspection

Date: 05/29/2024

Operator: MCCARTNEY ENGINEERING LLC - 55030

Location ID: 320422

Inspection Document #: 708201279

Adams County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: HSR-Fulenwider 4-10
Location ID: 320422



Photo 1. Erosion degradation occurring along the former access road; facing southeast towards the former location.

Inspection Photos
Location Name: HSR-Fulenwider 4-10
Location ID: 320422



Photo 2. Erosion degradation occurring along the former access road.

Inspection Photos
Location Name: HSR-Fulenwider 4-10
Location ID: 320422



Photo 3. Taken from the northern portion of the former location. Presence of undesirable vegetation (kochia) observed throughout.

Inspection Photos
Location Name: HSR-Fulenwider 4-10
Location ID: 320422



Photo 4. Taken near the former well location; see comments in Photo 3.

Inspection Photos
Location Name: HSR-Fulenwider 4-10
Location ID: 320422



Photo 5. Taken from the southern portion near the former well location; see comments in Photo 3.

Inspection Photos
Location Name: HSR-Fulenwider 4-10
Location ID: 320422



Photo 6. Bare/exposed soils observed near the former tank battery location; photo taken from the southeast corner.

Inspection Photos
Location Name: HSR-Fulenwider 4-10
Location ID: 320422



Photo 7. Bare/exposed soils observed near the former tank battery location; photo taken from the northwest corner.

Inspection Photos
Location Name: HSR-Fulenwider 4-10
Location ID: 320422



Photo 8. Erosion degradation occurring along the former access road; facing north.