

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/29/2024

Submitted Date:

05/31/2024

Document Number:

708201279**FIELD INSPECTION FORM**Loc ID 320422 Inspector Name: Edwardson, Dylan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 55030Name of Operator: MCCARTNEY ENGINEERING LLCAddress: 4251 KIPLING ST STE 575City: WHEAT RIDGE State: CO Zip: 80033**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
McCartney, Jack	303-830-7208	jack@mccartneyengineering.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203723	WELL	PA	09/21/2019	GW	001-09283	HSR-FULENWIDER 4-10	RI
320422	LOCATION	CL			-	HSR-FULENWIDER-62S66W 10NWNW	RI
470847	TANK BATTERY	CL	01/13/2020		-	Fulenwider Meter Tank Battery	RI

General Comment:

This is a Final Reclamation Inspection for PA Well API#001-09283. Well was plugged and abandoned 09/21/2019.

Environmental	
Spill/Remediation:	
Comment:	Remediation Project #13984 has been closed an approved under a Form 27 on 01/21/2020.
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB):	
Comment:	<div></div>
Pilot:	Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING

Comment

Corrective Action Date

1002b. SOIL REMOVAL AND SEGREGATION

Comment

Corrective Action Date

1002c. PROTECTION OF SOILS

Comment

Corrective Action Date

1002E. SURFACE DISTRURBANCE MINIMIZATION

Comment

Corrective Action Date

1003a. Waste and Debris removed?

Comment

Corrective Action Date

Unused or unneeded equipment onsite?

Comment

Corrective Action Date

Pit, cellars, rat holes and other bores closed?

Comment

Corrective Action Date

Guy line anchors marked?

Comment

Corrective Action Date

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed Pass

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: This location does not comply with Rule 1004. During this inspection, it was observed that the former location is not progressing towards reclamation standards with evidence of undesirable vegetation (e.g. kochia) and areas of bare/exposed soils. Refer to attached inspection photos.

Corrective Action: Comply with Rule 1004 to perform reclamation activities. Date **10/31/2024**

Overall Final Reclamation	Fail	Well Release on Active Location	<input type="checkbox"/>	Multi-Well Location	<input type="checkbox"/>
---------------------------	------	---------------------------------	--------------------------	---------------------	--------------------------

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Portions of the access road are experiencing erosion degradation (riling and gullyng) due to unstabilized soils. Refer to attached inspection photos.

Corrective Action: Comply with Rule 1002.f to repair/fix erosion degradation.

Date: 06/14/2024

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708201283	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6569626