

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/31/2024

Submitted Date:

05/31/2024

Document Number:

714201080**FIELD INSPECTION FORM**Loc ID 327796 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                   | Comment                         |
|--------------|-------|-------------------------|---------------------------------|
| ,            |       | ECMCInspections@Oxy.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 247364      | WELL | TA     | 03/14/2017  | OW         | 123-15161 | FRANK H21-15  | TA          |

**General Comment:**[THIS IS A WELLHEAD INSPECTION.](#)

**Location**Overall Good: ☒

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             | adequate |       |  |
| Corrective Action:   |          | Date: |  |

|                           |  |  |             |
|---------------------------|--|--|-------------|
| Emergency Contact Number: |  |  |             |
| Comment:                  |  |  |             |
| Corrective Action:        |  |  | Date: _____ |

|                           |   |       |            |
|---------------------------|---|-------|------------|
| <b>Good Housekeeping:</b> |   |       |            |
| Type                      | DEBRIS  |       |            |
| Comment:                  | debris in/outside of wellhead fencing. See attached photos. |       |            |
| Corrective Action:        | Comply with Rule 606.                                       | Date: | 06/14/2024 |

Overall Good: ☐

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

|                    |          |       |  |
|--------------------|----------|-------|--|
| <b>Fencing/:</b>   |          |       |  |
| Type               | WELLHEAD |       |  |
| Comment:           | iron     |       |  |
| Corrective Action: |          | Date: |  |

|                    |     |       |                 |
|--------------------|-----|-------|-----------------|
| <b>Equipment:</b>  |     |       | corrective date |
| Type: Plunger Lift | # 1 |       |                 |
| Comment:           |     |       |                 |
| Corrective Action: |     | Date: |                 |
| Type: Bradenhead   | # 1 |       |                 |
| Comment:           |     |       |                 |
| Corrective Action: |     | Date: |                 |

|                    |    |       |  |
|--------------------|----|-------|--|
| <b>Venting:</b>    |    |       |  |
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

Inspected Facilities

Facility ID: 247364

Type: WELL

API Number: 123-15161

Status: TA

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA; Form 6A in well file.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 12/19/2023

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 1

Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment   | User     | Date       |
|---|----------|------------|
| <div>ECMC Inspection Report Summary</div> <div>WEATHER CONDITIONS: cloudy, dry ground</div> <div>On Friday, May 31, 2024 at approximately 1200, I, Inspector Brittani Santistevan, conducted an on-site inspection at FRANK H21-15 (Kerr McGee Oil &amp; Gas Onshore), at location ID: 327796 in WELD COUNTY, Colorado.</div> <div>While there, I observed a TA wellhead.</div> <div>During this inspection the following possible compliance issues were observed:</div> <div>1. It appears to be debris inside/outside of wellhead fencing. Comply with Rule 606. (Corrective Actions Date: June 14, 2024) See attached photo #2.</div> <div>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</div> <div>This is a summary of inspection report.</div> | santistb | 05/31/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 714201081    | Photos      | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6571624">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6571624</a> |