

Inspection Photos
Location: Kamikaze 23-18
Facility ID: 309318



Photo 1 –Well placard




Photo 2 – Wellhead and equipment

Inspection Photos
Location: Kamikaze 23-18
Facility ID: 309318



Photo 3 – Location looking southeast



Photo 4 – Engine Skid and Spoil Pile

Inspection Photos
Location: Kamikaze 23-18
Facility ID: 309318



Photo 5 – Location Looking east



Photo 6 – Location Looking west

Inspection Photos
Location: Kamikaze 23-18
Facility ID: 309318



Photo 7 – Pit Facility ID 435026, Pit in the process for closure



Photo 8 – Pit in closure process

Inspection Photos
Location: Kamikaze 23-18
Facility ID: 309318



Photo 9 – Location Looking southwest

