

**Inspection Photos**  
**Location Name: William D. Lansdown unit D1**  
**Location ID: 318987**



**Photo 1 Location.**

**Photo 2 Stained soil by the WH.**

Inspection Photos  
Location Name: William D. Lansdown unit D1  
Location ID: 318987



Photo 3 WH sign.

Photo 4 Ancillary equipment.

Inspection Photos  
Location Name: William D. Lansdown unit D1  
Location ID: 318987



Photo 5 Stained soil around the pump jack base.

Photo 6 Stained soil around the pump jack base.

Inspection Photos  
Location Name: William D. Lansdown unit D1  
Location ID: 318987



Photo 7 Stained soil around the pump jack base.



Photo 8 Stained soil around the pump jack base.

Inspection Photos  
Location Name: William D. Lansdown unit D1  
Location ID: 318987



Photo 9 Tank battery location.



Photo 10 Horizontal heater treater.

Inspection Photos  
Location Name: William D. Lansdown unit D1  
Location ID: 318987



Photo 11 Stained soil inside the Horizontal heater Treater housing.



Photo 12 ECD.

Inspection Photos  
Location Name: William D. Lansdown unit D1  
Location ID: 318987



Photo 13 Stained soil by the flow line manifold & aux. pu.mp



Photo 14 Stained soil by the flow line manifold & aux. pump.

Inspection Photos  
Location Name: William D. Lansdown unit D1  
Location ID: 318987



Photo 15 Tank battery sign.

Photo 16 Stained soil by the tank battery.

Inspection Photos  
Location Name: William D. Lansdown unit D1  
Location ID: 318987



Photo 17 Tank battery.




Photo 18 Stained soil between the tanks

Inspection Photos  
Location Name: William D. Lansdown unit D1  
Location ID: 318987



Photo 19 Stained soil by tank load line valve .



Photo 20 Stained soil around the PW tanks

Inspection Photos  
Location Name: William D. Lansdown unit D1  
Location ID: 318987



Photo 21 Stained soil by PW tanks.



Photo 22 Gas Meter Run.