

**Storm Water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-17 Pad**  
**Location ID: 335248**



**Location Overview: Location is within High Priority/Density  
Habitat areas. Location is approximately 63 yards from a  
creek/drainage that contributes to the Colorado River.**

**Section/Township/Range: 17 6S94W**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-17 Pad**  
**Location ID: 335248**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-17 Pad**  
**Location ID: 335248**



**Photo # 8565 Stockpiled soils**



**Photo # 8566 Lack of stabilization/compaction**



**Storm Water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-17 Pad**  
**Location ID: 335248**



**Photo # 8567 Lack of stabilization/compaction**



**Photo # 8568 Lack of stabilization/compaction**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-17 Pad**  
**Location ID: 335248**



**Photo # 8569 Lack of stabilization/compaction**



**Photo # 8570 Lack of stabilization/compaction**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-17 Pad**  
**Location ID: 335248**



**Photo # 8571 Lack of stabilization/compaction**



**Photo # 8572 Lack of stabilization/compaction**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-17 Pad**  
**Location ID: 335248**



**Photo # 8573 Lack of stabilization/compaction**



**Photo # 8574 Lack of stabilization/compaction**