

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/30/2024

Submitted Date:

06/03/2024

Document Number:

694500664

FIELD INSPECTION FORM

Loc ID: 450391 Inspector Name: NEIDEL, KRIS On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	All Inspections
Graber, Nikki		nikki.graber@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428915	NONFACILITY	AC	05/15/2012		-	Walden Water Flood	EI

General Comment:

ECMC staff Kris Neidel inspected and observed sampling activities at the Walden Water Flood Facility, Facility 428915, Remediation Project # 7037 on 5/30/24. Weather was 60 degrees. CDH consulting staff was present to sample the monitoring wells that are a part of this Remediation project #7037. The Air Sparge/SVE system was "on" upon arrival and shut in for gauging and sampling. The SVE/Air sparge piping is all above ground poly pipe. The Air Sparge (injection) lines are smaller diameter. It was observed that many of the shut off valves on sparge wells were either closed or throttled (partly closed). It is unknown if this is by design or neglect. Corrective Actions: Submit an updated report on the design of the Air Sparge/SVE system. The operator should ensure that the wells and remediation system is functioning as designed.

Inspected Facilities

Facility ID: 428915 Type: NONFACILIT API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500665	photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6573970