

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/04/2024

Submitted Date:

06/04/2024

Document Number:

716400179

**FIELD INSPECTION FORM**

Loc ID 433040 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 555 17TH STREET SUITE 3700  
City: DENVER State: CO Zip: 80202

**Findings:**

25 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433041	WELL	PR	02/01/2019	OW	123-37435	Marcus State 3C-36H (M266)	PR
433043	WELL	PR	03/01/2019	OW	123-37437	Marcus State 3E-36H (M266)	PR
433045	WELL	PR	02/01/2019	OW	123-37439	Marcus State 3D-36H (M266)	PR
433046	WELL	PR	04/01/2019	OW	123-37440	Marcus State 3F-36H (M266)	PR
433049	WELL	PR	02/01/2019	OW	123-37442	Marcus State 3B-36H (M266)	PR
433050	WELL	PR	12/15/2013	OW	123-37443	Marcus State 3A-36H (M266)	PR

**General Comment:**

[This is a multi-well pad & tank battery inspection.](#)

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate, beginning to fade and will need to be updated in the near future		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate, beginning to fade and will need to be updated in the near future		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Hog fence shares with Ignitor		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog fence		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog fence		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Hog fence		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 6		

Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	card indicates current calibration		
Corrective Action:			Date:
Type: Emission Control Device	# 9		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 15		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 20		
Comment:	automation		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	OTHER	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	230 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	shares containment with the condensate tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	15	500 BBLS	STEEL AST		40.088500,-104.728470
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

**Wells Served By Facilities Above**

API Number
123-37440
123-37437
123-37435
123-37439
123-37442
123-37440

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 433041 Type: WELL API Number: 123-37435 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 05/08/2023 Annual Brhd Completed? No  
 Last Brhd Test Results Initial Surf Csg Pressure: 17 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: 0  
 Comment: Submit test results to the ECMC. Plumbed to surface.  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 433043 Type: WELL API Number: 123-37437 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 05/05/2023 Annual Brhd Completed? No  
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: 0  
 Comment: Submit test results to the ECMC. Plumbed to surface.  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 433045 Type: WELL API Number: 123-37439 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 05/05/2023 Annual Brhd Completed? No  
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: 0  
 Comment: Submit test results to the ECMC. Plumbed to surface.  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 433046 Type: WELL API Number: 123-37440 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 05/05/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Submit test results to the ECMC. Plumbed to surface.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 433049 Type: WELL API Number: 123-37442 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 05/05/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Submit test results to the ECMC. Plumbed to surface.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 433050 Type: WELL API Number: 123-37443 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 03/14/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: WATER H2O

End Surf Csg Pressure: 0

Comment: Submit test results to the ECMC. Plumbed to surface.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
This is a Routine Field Inspection. Any Corrective Actions from previous inspections not addressed are still applicable. Weather: Clear, partly cloudy Location: Dry	revasr	06/04/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716400180	Location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6574000">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6574000</a>