

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/04/2024

Submitted Date:

06/04/2024

Document Number:

715200328

**FIELD INSPECTION FORM**

Loc ID 321584 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 17180  
Name of Operator: CITATION OIL & GAS CORP  
Address: 14077 CUTTEN RD  
City: HOUSTON State: TX Zip: 77069

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Rogers, Bob	719-767-8851	brogers@cogc.com	
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207351	WELL	TA	11/01/2001	OW	017-06286	MCCORMICK 22-3 11	TA

**General Comment:**

5 Year MIT

Location				
<b>Lease Road:</b>				
	Type	Access		
	comment:	Two track through pasture		
	Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
	Type	WELLHEAD		
	Comment:	Lease sign by wellhead		
	Corrective Action:		Date:	
<b>Emergency Contact Number:</b>				
	Comment:	<input style="width: 100%;" type="text"/>		
	Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
	Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
	Type	OTHER		
	Comment:	Metal panels around solar panel and cathodic rectifier		
	Corrective Action:		Date:	
	Type	WELLHEAD		
	Comment:	Metal panels around wellhead		
	Corrective Action:		Date:	
<b>Equipment:</b>				
				corrective date
Type:	Ancillary equipment	# 2		
	Comment:	Electric panel and solar powered cathodic rectifier		
	Corrective Action:		Date:	
<b>Venting:</b>				
	Yes/No			
	Comment:			
	Corrective Action:		Date:	
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 207351 Type: WELL API Number: 017-06286 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: INITIAL CSG WAS DEAD. MIRU SGB SOLUTIONS. LOADED W/1BBL. PRESSURED CSG TO 365 PSIG. 5-MIN 365#. 10-MIN 365#. 15-MIN 365#. 0 PSI LOSS

Submit Form 21 (attached) within 30 days of MIT

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715200331	Form 21	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6574147">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6574147</a>