

Work Completion Report

Contractor: Peerless

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
6-3N-67W NWSW SANFORD TB		Armando Munoz	5/24/2024

Work Summary	Reclamation Type	Land Use
Repaired rutting and damage to berms at NE corner of pad due to storm water runoff. Recompect pull back all sediment that has migrated offsite. Mowed weed carcasses and picked up trash and debris.	Stormwater	Active Pad

One-Call Number	Red Zone Rep	Red Zone Date

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Stormwater Repairs	High	No	Location(s): SANFORD 13-6 Notes: Repari rutting and damage to berms at NE corner of pad due to stormwater runoff was observed. Area needs to be recompacted and recountoured. All sediment that has migrated offsite needs to be pulled back. Clean any weed carcasses and trash/debris throughout location.

COMPLETION DETAILS

Total Area Affected: **10,543 sq ft**
Seed Mix: **None used**
Crop Type: **Corn**
Soil Type: **Clay Loam**
Stabilization Date: **5/24/2024**
Seeding Date:
Mulch: **None**
Straw Bales: **NA**
Soil Amendment Type: **None**
Soil Amendment Rate: **NA**
Imported Top Soil: **NA**
Top Soil Source: **NA**
General Notes:

LOCATION INFO

Location(s) – Name: SANFORD 13-6

COGCC ID: **309986**
Well APIs at Location: **12325698**
Land Rep:
Land Owner: **James Warner**
Rec Contractor PO(s): **PEERLESS - TBD**
Vendor PO(s):
Billing Notes: **DJ-L0978**
Legal Address: **(WELD) NWSW 6 3N67W**
Topsoil Source:
Variance Notes:
Private Utility Notes:
Wildlife Restrictions:
General Notes:
COGCC Doc #'s:
Initial Reclaim Complete Date:
Maint. Reclaim Complete Date:

PHOTOS

Photo Name: Site Map

Description:




Photo Name: Pre-Completion

Description:



Photo Name: Post-Completion

Description:



Photo Name: SF2

Description:



Photo Name: SF3

Description:



Photo Name: SF4

Description:



Photo Name: SF5

Description:



Photo Name: SF6

Description:



Photo Name: SF7

Description:

