

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/05/2024

Submitted Date:

06/05/2024

Document Number:

696306394

**FIELD INSPECTION FORM**

Loc ID 452871 Inspector Name: PETRIE, ERICA On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10661  
Name of Operator: CIVITAS NORTH LLC  
Address: 555 17TH STREET #3700  
City: DENVER State: CO Zip: 80202

**Findings:**

- 18 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452981	WELL	PR	03/01/2020	OW	123-45842	Castor 8-59 19-24-12	PR
452985	WELL	PR	03/17/2020	OW	123-45846	Castor Fed 8-59 19-24-1	PR
452987	WELL	PR	03/17/2020	OW	123-45848	Castor Fed 8-59 19-24-6	PR
452989	WELL	PR	08/01/2023	OW	123-45850	Castor Fed 8-59 19-24-4	PR
452991	WELL	PR	08/01/2023	OW	123-45852	Castor Fed 8-59 19-24-3	PR
452994	WELL	PR	12/01/2023	OW	123-45855	Castor 8-59 19-24-16	PR

**General Comment:**

[This is a Well PAD and Production Facility Inspection](#)

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	24-Hour Emergency Contact Number on Wellhead Signs STILL shows Previous Operator's Contact Number; see photos		
Corrective Action:	Install sign to comply with Rule 605.d.		Date: <u>06/21/2024</u>

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 15		
Comment:			
Corrective Action:		Date:	
Type: VRT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		

Comment:	Instrumental Air Unit		Date:	
Corrective Action:			Date:	
Type: Bradenhead	# 6			
Comment:	Appear to be plumbed to surface		Date:	
Corrective Action:			Date:	
Type: Plunger Lift	# 6			
Comment:			Date:	
Corrective Action:			Date:	
Type: Emission Control Device	# 5			
Comment:			Date:	
Corrective Action:			Date:	
Type: LACT	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Compressor	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 7			
Comment:			Date:	
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	400 BBLs	STEEL AST		
Comment:					Date:
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with Crude Oil Tanks			Date:
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	OTHER	STEEL AST		40.645330,-104.012360
Comment:					Date:
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	750 BBLS	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 452981 Type: WELL API Number: 123-45842 Status: PR Insp. Status: PR

**Producing Well**

Comment:	PR	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 452985 Type: WELL API Number: 123-45846 Status: PR Insp. Status: PR

**Producing Well**

Comment:	PR	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 452987 Type: WELL API Number: 123-45848 Status: PR Insp. Status: PR

**Producing Well**

Comment:	PR	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 452989 Type: WELL API Number: 123-45850 Status: PR Insp. Status: PR

**Producing Well**

Comment:	PR	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 452991 Type: WELL API Number: 123-45852 Status: PR Insp. Status: PR

**Producing Well**

Comment:	PR	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 452994 Type: WELL API Number: 123-45855 Status: PR Insp. Status: PR

**Producing Well**

Comment:	PR	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
Routine Field Inspection	petrie	06/05/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696306395	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6575476">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6575476</a>