

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/03/2024

Submitted Date:

06/05/2024

Document Number:

707602915

**FIELD INSPECTION FORM**

Loc ID: 332069  
Inspector Name: Evins, Bret  
On-Site Inspection:   
2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**

ECMC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
332069	LOCATION	AC			-	LOUSTALET-65N64W 25NWSW	IO

**General Comment:**

This is a BATTERY inspection.  
Well(s): 2: Shut-In | SI.  
Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs (332069, 332056).  
(Well(s): 2: Shut-In | SI).

Centralized Battery Formerly served 3 Location IDs (305927, 323184, 332052).  
(Well(s): 3: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference (Associated Well(s), Battery Inspections):  
A.) Field Inspection Report doc. #707602907 and/or Location ID #332069 for SI Well(s) info.  
B.) Field Inspection Report doc. #707602909 and/or Location ID #332056 for SI Well(s) info.  
C.) Field Inspection Report doc. #707602911 and/or Location ID #305927 for PA Well(s) info.  
D.) Field Inspection Report doc. #707602913 and/or Location ID #332052 for PA Well(s) info.  
E.) Field Inspection Report doc. #707602915 and/or Location ID #332069 for Battery / Facility, Equipment info.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Surrounded by metal berms.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Ancillary equipment	# 1		corrective date
Comment:	Battery site: 1: ECD scrubber(s).		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Gas Sales: Calibration card(s) indicates calibration > 1 year. (PDC). Last calibration: 05/23/2022. Inactive, NO production.		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	Crude storage vapor line combustor(s). Controls crude oil tank(s) vapors. Pilots: OFF   Shut-down.		

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	<a href="#">Centralized Battery serves 2 Location IDs (332069, 332056). (Well(s): 2: Shut-In   SI). Centralized Battery serves 1 Tank Battery Facility ID (Pending).</a>				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	<a href="#">Berms shared w/ crude oil tank(s), produced H2O tank(s).</a>				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.363220,-104.506997

Comment:		
Corrective Action:		Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms shared w/ crude oil tank(s), produced H2O tank(s).			
Corrective Action:				Date:

**Wells Served By Facilities Above**

**AirsID**

API Number	API Number	AirsID
123-21774		
123-21789		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 332069 Type: LOCATION API Number: - Status: AC Insp. Status: IO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><a href="#">CECMC Inspection Report Synopsis:</a></p> <p>On MON 06/03/2024 at approximately 17:39 hrs. I, Bret Evins, conducted an onsite inspection at:                      Operator Name: PDC ENERGY INC                      Facility Name: Pending                      Facility ID: Pending                      Location Name: LOUSTALET-65N64W/25NWSW                      Location ID: 332069                      Well Name(s):                      See photo(s) #6 attached to this report.                      API:                      See "Wells Served By Facilities Above" sec on pg. 4, and/or photo(s) #6 attached to this report.                      Location County: Weld County, Colorado                      Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed:                      Well(s): 2: Shut-In   SI.                      Battery: Inactive   Shut-down.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	06/05/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602916	Site photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6575616">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6575616</a>