

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GV 88-1 Frac Pit 1

Location ID: 334734



Photo # 9444 From entrance to location



Photo # 9445 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GV 88-1 Frac Pit 1

Location ID: 334734



Photo # 9446 Location



Photo # 9447 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GV 88-1 Frac Pit 1

Location ID: 334734



Photo # 9448 Location



Photo # 9449 Corroded/failed piping

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GV 88-1 Frac Pit 1

Location ID: 334734



Photo # 9450 Corroded/failed piping



Photo # 9451 Corroded/failed piping

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GV 88-1 Frac Pit 1

Location ID: 334734



Photo # 9452 Corroded/failed piping



Photo # 9453 Corroded/failed piping

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GV 88-1 Frac Pit 1

Location ID: 334734



Photo # 9454 Corroded/failed piping



Photo # 9455 Open ended piping/wildlife hazard/available for entry by wildlife

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GV 88-1 Frac Pit 1

Location ID: 334734



Photo # 9456 Open ended load line



Photo # 9457 Open ended piping/wildlife hazard/available for entry by wildlife

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GV 88-1 Frac Pit 1

Location ID: 334734



Photo # 9458 Stored farm equipment



Photo # 9459 Stored farm equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GV 88-1 Frac Pit 1

Location ID: 334734



Photo # 9460 Barbed wire fence around location needs maintenance/wildlife hazard



Photo # 9461 Barbed wire fence around location needs maintenance/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GV 88-1 Frac Pit 1

Location ID: 334734



Photo # 9462 Barbed wire fence around location needs maintenance/wildlife hazard



Photo # 9463 Barbed wire fence around location needs maintenance/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GV 88-1 Frac Pit 1

Location ID: 334734



Photo # 9464 Barbed wire fence around location needs maintenance/wildlife hazard



Photo # 9465 Barbed wire fence around location needs maintenance/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GV 88-1 Frac Pit 1

Location ID: 334734



Photo # 9466 Barbed wire fence around location needs maintenance/wildlife hazard



Photo # 9467 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GV 88-1 Frac Pit 1

Location ID: 334734



Photo # 9468 Debris



Photo # 9469 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GV 88-1 Frac Pit 1

Location ID: 334734



Photo # 9470 Debris



Photo # 9471 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GV 88-1 Frac Pit 1

Location ID: 334734



Photo # 9472 Debris



Photo # 9473 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GV 88-1 Frac Pit 1

Location ID: 334734



Photo # 9474 Debris



Photo # 9475 Debris