

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/05/2024

Submitted Date:

06/06/2024

Document Number:

708903985

FIELD INSPECTION FORM

Loc ID: 334781
Inspector Name: Smelser, Wayne
On-Site Inspection:
2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

37 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287934	WELL	PR	07/19/2007	GW	045-13121	FOSSIL CREEK RWF 522-6	PR
287935	WELL	PR	07/19/2007	GW	045-13120	FOSSIL CREEK RWF 422-6	PR
287936	WELL	PR	06/30/2008	GW	045-13119	FOSSIL CREEK RWF 322-6	PR
287937	WELL	PR	06/30/2008	GW	045-13118	FOSSIL CREEK RWF 22-6	PR
287938	WELL	PR	08/18/2008	GW	045-13117	FOSSIL CREEK RWF 512-6	PR
287939	WELL	PR	07/19/2007	GW	045-13116	FOSSIL CREEK RWF 412-6	PR
287940	WELL	PR	07/19/2007	GW	045-13115	FOSSIL CREEK RWF 312-6	PR
287941	WELL	PR	07/19/2007	GW	045-13114	FOSSIL CREEK RWF 11-6	PR
287942	WELL	PR	07/19/2007	GW	045-13113	FOSSIL CREEK RWF 12-6	PR
287943	WELL	PR	05/01/2022	GW	045-13112	FOSSIL CREEK RWF 311-6	PR
287944	WELL	PR	07/19/2007	GW	045-13111	FOSSIL CREEK RWF 411-6	PR
287945	WELL	PR	07/19/2007	GW	045-13110	FOSSIL CREEK RWF 511-6	PR
287946	WELL	PR	07/19/2007	GW	045-13109	FOSSIL CREEK RWF 521-6	PR
287948	WELL	PR	07/19/2007	GW	045-13108	FOSSIL CREEK RWF 421-6	PR
287949	WELL	PR	07/19/2007	GW	045-13107	FOSSIL CREEK RWF 321-6	PR
287950	WELL	PR	07/19/2007	GW	045-13106	FOSSIL CREEK RWF 21-6	PR

General Comment:

CECMC Inspection Report Summary

On 06/05/2024 at approximately 13:48 hours, I, Compliance Specialist, Wayne Smelser
Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 11-6 Pad.
Location # 334781 in Garfield County Colorado.
Location is within High Priority/Density/Black Bear Habitat areas.
While there, I observed normal production operations.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Small amount of staining near 4-5 wellheads		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels		

Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical tanks - hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Gas Meter Run	# 16		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 16		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bradenhead	# 16		
Comment:	RWF 512-6 & RWF 522-6 wells have Taylor plugs located on bradenheads, bradenhead valves are accessible. Remaining 14 wells have no form of pressure monitoring equipment located on bradenheads, bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	3 marked deadman & 1 unmarked deadman All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 16		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Summit Midstream		
Corrective Action:		Date:	

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLs	STEEL AST			
Comment: Tank equipped with telemetry						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient				
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 287934 Type: WELL API Number: 045-13121 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
 Comment: Shut In
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287935 Type: WELL API Number: 045-13120 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287936 Type: WELL API Number: 045-13119 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287937 Type: WELL API Number: 045-13118 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287938 Type: WELL API Number: 045-13117 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287939 Type: WELL API Number: 045-13116 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287940 Type: WELL API Number: 045-13115 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287941 Type: WELL API Number: 045-13114 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 287942 Type: WELL API Number: 045-13113 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 287943 Type: WELL API Number: 045-13112 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 287944 Type: WELL API Number: 045-13111 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 287945 Type: WELL API Number: 045-13110 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 287946 Type: WELL API Number: 045-13109 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 287948 Type: WELL API Number: 045-13108 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 287949 Type: WELL API Number: 045-13107 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287950 Type: WELL API Number: 045-13106 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Culverts						
		Culverts				
				Material Handling And Spill Prevention		Chemical tank containments
Berms						
Retention Ponds						
		Ditches				
		Compaction				
Compaction						Small areas of light compaction
Gravel						Sparse to none in most areas
		Gravel				Sparse to none in sections

Comment: [1. Some fluid in chemical tank containment, may need maintenance in the near future.](#)
[2. Irrigation water running across small section of lease road near entrance to location.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Housekeeping, Equipment & Stormwater for comments.	smelserw	06/06/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708903986	Inspection 708903985 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6576043
708903987	Inspection 708903985 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6576044