

Inspection Photos
Location Name: Linnebur 4
Location ID: 319762

Jun 5, 2024 at 12:06:17 PM
39.961818,-103.935741
ECMC



Pic 1 pumpjack

Jun 5, 2024 at 12:07:43 PM
39.962187,-103.935544
ECMC



Pic 2 contaminated soil / weeds unmanaged / wellhead sign is incorrect information.

Inspection Photos
Location Name: Linnebur 4
Location ID: 319762



Pic 3 no containment under chemical tank



Pic 4 contaminated soil by exhaust needs to be removed

Inspection Photos
Location Name: Linnebur 4
Location ID: 319762

Jun 5, 2024 at 12:09:40 PM
39.962258,-103.935637
ECMC



Pic 5 no guy line anchor marker

Jun 5, 2024 at 12:11:12 PM
39.962608,-103.936907
ECMC



Pic 6 riser located east of pump jack no LOTO

Inspection Photos
Location Name: Linnebur 4
Location ID: 319762



pic 7 Riser east of pump jack, arrow shows pump jack



Pic 8 tanks, berms need to be repaired

Inspection Photos
Location Name: Linnebur 4
Location ID: 319762



Pic 9 Sign is inadequate at tank battery.




Pic 10 contaminated soil by valve on tank needs to be removed

Inspection Photos
Location Name: Linnebur 4
Location ID: 319762



Pic 11 separator, propane tank



Pic 10 Separator plumbing

Inspection Photos
Location Name: Linnebur 4
Location ID: 319762



Pic 11 OOSLOT riser needs to be LOTO



Pic 12 BV leading to pit

Inspection Photos
Location Name: Linnebur 4
Location ID: 319762



Pic 13 Pit needs weeds removed