

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/06/2024

Submitted Date:

06/06/2024

Document Number:

699505911

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 31257
Name of Operator: FRITZLER RESOURCES INC
Address: P O BOX 114
City: FORT MORGAN State: CO Zip: 80701

Findings:

- 11 Number of Comments
- 7 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Brown, Kari		kari.oakman@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Silver, Randy		randy.silver@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
,		gfritzler@bresnan.net	
Graber, Nikki		nikki.graber@state.co.us	
Burn, Diana		diana.burn@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203117	WELL	SI	02/01/2016	GW	001-08525	LINNEBUR 24-1	SI

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Pit appears to be closed on location, provide form 27, no form 27 on file. Pit was observed on previous inspections.		
Corrective Action:	Comply with rule 911 a	Date:	06/06/2024
Type			
Comment:	OOSLOT risers not tagged		
Corrective Action:	Comply with rule 1105	Date:	06/06/2024
Type	OTHER		
Comment:	wellhead sign inadequate		
Corrective Action:	Comply with rule 605 d.	Date:	06/06/2024
Type	OTHER		
Comment:	stormwater damage on south end of location by wellhead		
Corrective Action:	Comply with rule 1002.f.(2)C	Date:	06/06/2024
Type	OTHER		
Comment:	Berms inadequate around tank		
Corrective Action:	Comply with rule 603 o.	Date:	06/06/2024
Type	WEEDS		
Comment:	Weeds unmanaged on locaion		
Corrective Action:	Comply with rule 606	Date:	06/06/2024
Type	OTHER		
Comment:	access		
Corrective Action:	Comply with rule 204	Date:	06/06/2024

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	plumbed to surface		

Corrective Action:	Date:
--------------------	-------

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		

Comment:	Date:
Corrective Action:	Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Berms need repair				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 203117 Type: WELL API Number: 001-08525 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 11/21/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
1002.f.(2)C	medinaj	06/06/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699505912	Inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6577141