

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/06/2024

Submitted Date:

06/06/2024

Document Number:

699505915

FIELD INSPECTION FORM

Loc ID: 319762 Inspector Name: MEDINA, JUSTIN On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 31257
Name of Operator: FRITZLER RESOURCES INC
Address: P O BOX 114
City: FORT MORGAN State: CO Zip: 80701

Findings:

- 15 Number of Comments
- 9 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		gfritzler@bresnan.net	
Burn, Diana		diana.burn@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Silver, Randy		randy.silver@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201286	WELL	PR	05/01/2023	OW	001-06689	LINNEBUR 4	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Wellhead sign incorrect.		
Corrective Action:	Comply with rule 605 d	Date:	06/06/2024
Type	WEEDS		
Comment:	Weeds unmanaged on location		
Corrective Action:	comply with rule 606	Date:	06/06/2024
Type	OTHER		
Comment:	Sign at tank batter is inadequate		
Corrective Action:	Comply with rule 605 a	Date:	06/06/2024
Type	OTHER		
Comment:	Risers on location are not LOTO		
Corrective Action:	Comply with rule 1105	Date:	06/06/2024
Type	OTHER		
Comment:	no gas measurement equipment on location, provide how gas is measured on location, no midstream equipment		
Corrective Action:	Comply with rule 430	Date:	06/06/2024
Type	OTHER		
Comment:	Contaminated soil near wellhead and loutout line		
Corrective Action:	Comply with rule 905 e	Date:	06/06/2024
Type	OTHER		
Comment:	No production records since 12/1/23		
Corrective Action:	Comply with rule 429	Date:	06/06/2024
Type	OTHER		
Comment:	Guy line anchor is not marked		
Corrective Action:	Comply with rule 1003 a	Date:	06/06/2024
Type	OTHER		
Comment:	Locks on gate, unable to access location		
Corrective Action:	Comply with rule 204	Date:	06/06/2024

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	6' hog fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	gas motor		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:	one needs to be marked		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	plumbed to surface		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 201286 Type: WELL API Number: 001-06689 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/21/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: None Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard:

Comment:

Corrective Action

Date:

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On 6/5/24 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Linnebur 4 Company Name- Fritzler Resources API- 05-001-06689 In Adams County Colorado. While there, I observed PR well, no production data since 12/1/2023 During this inspection the following possible compliance issues were observed: Weeds. Rule 606. 6/6/24 Contaminated soil. Rule 905 e. 6/6/24 Access. Rule 204. 6/6/24 Wellhead sign. Rule 605d. 6/6/24 Sign at Tanks battery. Rule605 a. 6/6/24 OOSLOT risers. Rule 1105. 6/6/24 Guy Line Anchor Marker. Rule 1003 a. 6/6/24 Oil production reporting. Rule 429. 6/6/24 No gas measurement equipment. Rule 430. 6/6/24</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p>	medinaj	06/06/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699505916	inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6577143