

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/06/2024

Submitted Date:

06/06/2024

Document Number:

716400189

FIELD INSPECTION FORMLoc ID 318314 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	All Inspections
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241094	WELL	PR	01/01/2024	GW	123-08882	SUCKLA FARMS C 3	PR

General Comment:[This is a wellsite inspection.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well information is faded and not legible.		
Corrective Action:	Install/Replace sign to comply with Rule 605.g.	Date:	08/06/2024

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Good Housekeeping:

Type			
Comment:	some vegetaion around the ancillary equip. & the PJ base need to be addressed.		
Corrective Action:		Date:	

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	fabricated angle iron		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	barb wire		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Ancillary equip. has fabricated steel pipe and round stock.		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Ancillary equipment	# 1		
Comment:	Electric panel(shut off), meter box and transformers,		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Inspector Name: Revas, Robbie

Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	241094	Type:	WELL	API Number:	123-08882	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR the electric panel is shut off.								
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	01/24/2024		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	0		Fluid Type:					
	End Surf Csg Pressure:	0							
Comment:	plumbed to surface.								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <input type="text"/>						Date: <input type="text"/>
Corrective Action: <input type="text"/>						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments

Comment	User	Date
ECMC Inspection Report Summary On Thursday 6-6-2024 at approximately 1200 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Operator: KP Kauffman Location name: Location ID # 318314 Well Name: Suckla Farms C3 API # 05-123-08882 County: Weld Weather: Clear Location: Dry While there, I observed a wellsite, PR at the time of the inspection. During this inspection, I observed the following possible compliance issues: 605.g. Signs: CA date 8-6-2024 See attached photos. A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.	revasr	06/06/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716400190	Location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6577311