

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 31-6 Pad

Location ID: 334988



Photo # 44 From entrance to location



Photo # 45 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 31-6 Pad

Location ID: 334988



Photo # 46 Location



Photo # 47 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 31-6 Pad

Location ID: 334988



Photo # 48 Location



Photo # 49 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 31-6 Pad

Location ID: 334988



Photo # 50 Location



Photo # 51 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 31-6 Pad

Location ID: 334988



Photo # 52 Location



Photo # 53 Mechanical Condition - Possible leak on PA 332-6 wellhead casing valve

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 31-6 Pad

Location ID: 334988



Photo # 54 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 55 PRV vent line does not comply with CECMC pressure safety device rules