

**Comment:** Unused oil and gas piping equipment observed on location.  
**Piping has been removed from location.**



**Comment:** Impacted surface material observed at the pump jack muffler and well head.  
**Maintenance has been completed and impacted soil has been removed and disposed of.**





**Comment:** Storm water corrective action identified in the previous inspection doc #714000032 has only been partially addressed. New storm water divergent channel has not been installed per good engineering practices, erosion is occurring through the new channel and additional stabilization is needed.

**Storm water diversion has been stabilized with aggregate to minimize erosion in channel.**



